



Telephone: 867 777-8900

Fax: 867-777-2090

September 20, 2017

Chinook Energy Inc
Suite 1000, 517-10th Avenue SW
Calgary, AB T2R 0A8

Attention: Darren Tomecek

File Number **G02A012**
Type of Operation **OIL AND GAS DRILLING - WELLSITE**
Location **Ontaratue River D-39**

To: Darren Tomecek,

An inspection of the above noted operation was conducted on September 19, 2017 by Manager, Resource Management Donald Arey and Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent, Beaufort Delta Region
GLWB

ENVIRONMENTAL INSPECTION REPORT

FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF September 21, 2016

Await updated sample report from sump prior to a final inspection.

Permittee:	Chinook Energy Inc	Permit Expiry Date:	December 31, 2005
Land Use Permit No.	G02A012	Previous Inspection:	September 21, 2016
Quarrying Permit No.		Inspection Date:	September 19, 2017
Contractor:		Subcontractor:	
Location(s) Inspected:	Ontaratue River D-39		
Current Stage of Operation:	Completed and monitoring		
Program Modifications Approved:	NIL		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	D39				
Erosion (Control or Prevention)	A				
Wildlife and Fisheries Habitat (Protection)	A				
Ecological Resources	A				
Location as Permitted	A				
Time as Permitted	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Methods & Techniques	A				
Facilities	A				

Explanatory Remarks -

D39:

No change observed since last inspection dated Sept 22, 2016, except that very little ponded water was on site to the North west and South east corners of the sump. Nothing evident in regards to any subsidence, all looked satisfactory at the time of the inspection.

It is again requested that a sump assessment be provided as previously requested in last inspection report dated Sept. 22, 2016 to ensure on sumps integrity.

MATTERS FOR FOLLOW UP

that a sump assessment be provided as previously requested in last inspection report dated Sept. 22, 2016 to ensure on sumps integrity.

N/A

Representative Signature



Inspector's Signature

Date:	September 19, 2017	Permit #:	G02A012	Page No:	1
-------	--------------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6



Date:	September 19, 2017	Permit #:	G02A012	Page No:	4
-------	--------------------	-----------	---------	----------	---