



Telephone: 867 777-8900

Fax: 867-777-2090

September 20, 2017

Chinook Energy Inc.  
Suite 1000, 517-10th Avenue SW  
Calgary, AB T2R 0A8

**Attention: Darren Tomecek**

**File Number** G02A013  
**Type of Operation** OIL AND GAS DRILLING - WELLSITE  
**Location** Thunder River N-73

To: Darren Tomecek,

An inspection of the above noted operation was conducted on September 19, 2017 by Manager, Resource Management Donald Arey and Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey  
Manager, Resource Management  
Department of Lands  
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent, Beaufort Delta Region  
GLWB

### ENVIRONMENTAL INSPECTION REPORT

FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF September 21, 2016  
 check vegetation cover and await final plan.

<b>Permittee:</b>	Chinook Energy Inc.	<b>Permit Expiry Date:</b>	December 31, 2005
<b>Land Use Permit No.</b>	G02A013	<b>Previous Inspection:</b>	September 21, 2016
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	September 19, 2017
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	Thunder River N-73		
<b>Current Stage of Operation:</b>	completed and restored		
<b>Program Modifications Approved:</b>	NIL		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	<b>N73</b>				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Location as Permitted	A				
Time as Permitted	A				

Explanatory Remarks -

N73:

During the inspection it was observed that the sump had more vegetation cover from previous inspection done on Sept. 21 2016. The sump was solid with no evidence of any subsidence.


As previously requested in last inspection report dated Sept 22, 2016 a final plan is required prior to conducting a final inspection to recommend closure.

**MATTERS FOR FOLLOW UP**

await final plan

N/A

Representative Signature



Inspector's Signature



# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





# ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

