



Telephone: 867 777-8900  
Fax: 867-777-2090

May 13, 2016

Bob's Welding Ltd.  
P.O. Box 2644  
Inuvik, NT X0E 0T0

Attention: Lyle Gully

File Number: G11Q001  
Type of Operation: QUARRY SITE - Existing  
Location: Km 251 Dempster Highway

To: Lyle Gully,

An inspection of the above noted operation was conducted on May 11, 2016 by Manager, Resource Management Donald Arey.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey  
Manager, Resource Management  
Department of Lands  
Beaufort Delta Region

CC: GLWB



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	Bob's Welding Ltd.	<b>Permit Expiry Date:</b>	March 31, 2016
<b>Land Use Permit No.</b>	G11Q001	<b>Previous Inspection:</b>	September 10, 2015
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	May 11, 2016
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	Km 251 Dempster Highway		
<b>Current Stage of Operation:</b>	completed		
<b>Program Modifications Approved:</b>	Applications in for LUP and QP		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	<b>Km 251</b>				
Equipment as Approved (Type & Size)	N/I				
Methods & Techniques	U				
Chemicals	A				
Fuel Storage	N/A				
Matters not Inconsistent	A				
Location as Permitted	A				
Time as Permitted	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

**Explanatory Remarks -**

**Km 251 :**

On Sept 10 2015 no concerns was observed with the quarrying operation, but contractor was informed that no new QP will be issued until such time all material quarried is removed from site.

During this inspection it was observed that removal of material is continuing, and previous blast was still being pushed off the benches. It was understood and observed from last inspection that the material was being removed up until it began to freeze together. It was understood that as result of the bulkiness of material being frozen further removal and scraping could not be completed over the winter season.

A new Quarry Permit will be issued to remain in compliance. A clause indicating that no drilling and/or blasting will occur until such time all material from permit # 2014QP0023 is removed from site.

It should be understood that if any drilling or blasting occurs during removal of previous material taken under quarry permit no. 2014QP0023, the Department of Lands will have to issue a stop work order due to noncompliance issues.



### ENVIRONMENTAL INSPECTION REPORT

*N/A*

Representative Signature

*[Handwritten Signature]*

Inspector's Signature



# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

**Figure 1**

**material from previous blast being pushed over**



**Figure 2**

**view of stock piles**





# ENVIRONMENTAL INSPECTION REPORT

**Figure 3**  
Pit Floor



**Figure 4**  
material from previous blast being pushed over

