



Telephone: 867-777-8907
Fax: 867-777-2090

March 8, 2019

GNWT Department of Infrastructure
Bag Service #1
Inuvik, NT X0E 0T0

Attention: **Mohammad Hossain**

File Number G13H004
Type of Operation FUEL CACHES
Location James Creek

Dear Mohammad Hossain,

An inspection of the above noted operation was conducted on March 06, 2019 by Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC:

Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region

GLWB



ENVIRONMENTAL INSPECTION REPORT

Permittee:	GNWT Department of Infrastructure	Permit Expiry Date:	August 11, 2020
Land Use Permit No.	G13H004	Previous Inspection:	February 20, 2019
Quarrying Permit No.		Inspection Date:	March 06, 2019
Contractor:	DOI	Subcontractor:	
Location(s) Inspected:	James Creek		
Current Stage of Operation:	On-going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	James Creek			
Wildlife and Fisheries Habitat (Protection)	A			
Wastes	A			
Location as Permitted	A			
Time as Permitted	A			
Equipment as Approved (Type & Size)	A			
Methods & Techniques	A			
Facilities	A			
Erosion (Control or Prevention)	A			
Chemicals	U			
Fuel Storage	A			
Restoration of Lands	A			
Permits	A			
Matters not Inconsistent	A			
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A			

Explanatory Remarks - James Creek:

During the inspection on March 6, 2019 at the James Creek Maintenance camp there were a couple of concerns observed by the inspector.

The large storage container of used oil has not been placed in a secondary containment or removed as requested in the last inspection report dated February 20, 2019.

There is some spills in 2 places on site which look like hydraulic fluid, 1 near the fueling pump and 1 at the garage door entrance closest to the fueling pump. The rest of the site looks in good order.

Please have these issues dealt with in a timely manner.



Representative Signature



Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

