



Telephone: 867-777-8907

Fax: 867-777-2090

October 12, 2018

GNWT Department of Infrastructure  
Bag Service #1  
Inuvik, NT XOE OTO

Attention: **Jahangir Hossain**

**File Number** G13H004  
**Type of Operation** FUEL CACHES  
**Location** James Creek Km 14.2

Dear Jahangir Hossain,

An inspection of the above noted operation was conducted on October 11, 2018 by Resource Management Officer II Herbert Allen and Resource Management Officer I Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen  
Resource Management Officer II  
Department of Lands  
Beaufort Delta Region

CC:

Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region  
GLWB



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	GNWT Department of Infrastructure	<b>Permit Expiry Date:</b>	August 11, 2020
<b>Land Use Permit No.</b>	G13H004	<b>Previous Inspection:</b>	September 25, 2018
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	October 11, 2018
<b>Contractor:</b>	DOI	<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	James Creek Km 14.2		
<b>Current Stage of Operation:</b>	on-going		
<b>Program Modifications Approved:</b>			

**Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected**

Operating Condition	Aspect Inspected			
	James Creek			
Wildlife and Fisheries Habitat (Protection)	A			
Wastes	A			
Location as Permitted	A			
Time as Permitted	A			
Equipment as Approved (Type & Size)	A			
Methods & Techniques	A			
Facilities	A			
Erosion (Control or Prevention)	A			
Chemicals	U			
Fuel Storage	A			
Restoration of Lands	U			
Permits	A			
Matters not Inconsistent	A			
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A			

**Explanatory Remarks -**

James Creek:

During the inspection on October 11, 2018 at James Creek camp there were a couple of concerns that were not addressed from previous inspection reports.

The hydraulic fluid in the end dump ram was not drained or capped and now there is a spill under the ram. With snow cover in the area, it is unknown how much is on the ground under the ram. The canvas material beside the land farm was not removed as requested in the August 23, 2018 and September 25, 2018 inspection reports. If this end dump is not on the equipment list for the Land Use permit for this site then it should be removed.

Over all the site looks clean and in good order.

WA

Representative Signature

Inspector's Signature

Date:	October 11, 2018	Permit #:	G13H004	Page No:	1
-------	------------------	-----------	---------	----------	---





# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2







# ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

