



Telephone: 867-777-8907
Fax: 867-777-2090

September 26, 2018

GNWT Department of Infrastructure
Bag Service #1
Inuvik, NT XOE 0T0

Attention: Jahangir Hossain

File Number: G13H004
Type of Operation: FUEL CACHES
Location: James Creek Km 14.2

Dear Jahangir Hossain,

An inspection of the above noted operation was conducted on September 25, 2018 by Resource Management Officer II Herbert Allen and Resource Management Officer I Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC:
Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region

GLWB



ENVIRONMENTAL INSPECTION REPORT

Permittee:	GNWT Department of Infrastructure	Permit Expiry Date:	August 11, 2018
Land Use Permit No.	G13H004	Previous Inspection:	September 12, 2018
Quarrying Permit No.		Inspection Date:	September 25, 2018
Contractor:	DOI	Subcontractor:	
Location(s) Inspected:	James Creek Km 14.2		
Current Stage of Operation:	On-going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	James Creek				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Fuel Storage	U				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

Explanatory Remarks -

James Creek:

During the inspection on September 25, 2018 at James Creek camp there were a couple of concerns that were not addressed from previous inspection reports.

The hydraulic fluid in the end dump ram was not drained or capped and can still create a spill with snow displacement. With snow cover in the area, it is unknown if the spill on the ground under the ram was cleaned up. The canvas material beside the land farm was not removed as requested in the August 23, 2018 inspection report.

Over all the site looks clean and in good order.

Representative Signature

Inspector's Signature

Date:	September 25, 2018	Permit #:	G13H004	Page No:	1
-------	--------------------	-----------	---------	----------	---




ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

