



Telephone: 867 777-8900
Fax: 867-777-2090

October 21, 2016

GNWT Department of Transportation
P.O. Box 2038
Inuvik, NT X0E 0T0

RECEIVED
OCT 31 2016

Attention: Arvind Vashishtha

File Number: G13H004
Type of Operation: FUEL CACHES
Location: Km 14.2 James Creek

To: Arvind Vashishtha,

An inspection of the above noted operation was conducted on October 20, 2016 by Manager, Resource Management Donald Arey.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC: Conrad Baetz, Superintendent Dept of Lands, Beaufort Delta Region
GLWB



ENVIRONMENTAL INSPECTION REPORT

Permittee:	GNWT Department of Transportation	Permit Expiry Date:	August 11, 2018
Land Use Permit No.	G13H004	Previous Inspection:	October 06, 2016
Quarrying Permit No.		Inspection Date:	October 20, 2016
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 14.2 James Creek		
Current Stage of Operation:	ongoing		
Program Modifications Approved:	NIL		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	James Creek Km 14.2			
Wastes	U			
Facilities	A			
Chemicals	A			
Fuel Storage	A			
Location as Permitted	A			
Equipment as Approved (Type & Size)	A			

Explanatory Remarks -

James Creek Km 14.2:

During this inspection it was observed that some of the concerns from the previous inspection report have been dealt with in regards to the garbage at the back end of the site have been removed. It was also observed that some of the waste oil pails had also been removed. It is recommend that these smaller items of concern such as the waste oil pails and batteries be dealt A.S.A.P. prior to freeze up of which will be more difficult to remove.

On the previous inspection report it was requested that a detailed final report be provided, this report has not been provided or any indication in writing as to when this will be done.

MATTERS FOR FOLLOW UP

Ensure final report for clean up is provided.

N/A

Representative Signature

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Old tanks on site to be removed at a later date.



Figure 2

waste area





ENVIRONMENTAL INSPECTION REPORT

Figure 3
silt fence



Figure 4
old battery storage to be removed





ENVIRONMENTAL INSPECTION REPORT

Figure 5
waste oil to be removed



Figure 6
land farm

