



Telephone: 867-777-8907

Fax: 867-777-2090

April 10, 2018

GNWT Department of Infrastructure
Bag Service #1
Inuvik, NT X0E 0T0

Attention: Jahangir Hossain

File Number	G14E002
Type of Operation	QUARRY SITE - Existing
Location	Wrangling River (178.7)

Dear Jahangir Hossain,

An inspection of the above noted operation was conducted on April 09, 2018 by Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC:

Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region

GLWB



ENVIRONMENTAL INSPECTION REPORT

Permittee:	GNWT Department of Infrastructure	Permit Expiry Date:	May 24, 2019
Land Use Permit No.	G14E002	Previous Inspection:	March 28, 2018
Quarrying Permit No.		Inspection Date:	April 09, 2018
Contractor:		Subcontractor:	
Location(s) Inspected:	Wrangling River (178.7)		
Current Stage of Operation:	Stock piling completed		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Km 178.7				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Erosion (Control or Prevention)	A				
Wildlife and Fisheries Habitat (Protection)	A				
Restoration of Lands	A				
Permits	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

Explanatory Remarks - Km 178.7:

During the inspection on April 9, 2018 there were no concerns observed by the inspector. It appeared at the time of the inspection all the hauling of the material to the site was completed.

The material that was stored close to the bank to the river was pushed back to a satisfactory distance. The site was left clean and there were no concerns from the inspector.

NA

Representative Signature

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Gravel near the edge of the bank to the creek is moved to a greater distance



Figure 2

Viewing east



Date:	April 09, 2018	Permit #:	G14E002	Page No:	2
-------	----------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Figure 3
Viewing north



Figure 4
Viewing south

