



Telephone: 867-777-8907

Fax: 867-777-2090

August 1, 2018

GNWT Department of Infrastructure
Bag Service #1
Inuvik, NT XOE OT0

Attention: **Jahangir Hossain**

File Number G14E002
Type of Operation QUARRY SITE - Existing
Location Km 178.1

Dear Jahangir Hossain,

An inspection of the above noted operation was conducted on July 31, 2018 by Resource Management Officer II Herbert Allen and Resource Management Officer I Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC:

Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region

GLWB

Bag Service 1, Inuvik, NT XOE OT0



ENVIRONMENTAL INSPECTION REPORT

Permittee:	GNWT Department of Infrastructure	Permit Expiry Date:	May 24, 2019
Land Use Permit No.	G14E002	Previous Inspection:	July 25, 2018
Quarrying Permit No.		Inspection Date:	July 31, 2018
Contractor:	DOI	Subcontractor:	
Location(s) Inspected:	Km 178.1		
Current Stage of Operation:			
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected
	Km 178.1
Location as Permitted	A
Time as Permitted	A
Equipment as Approved (Type & Size)	A
Methods & Techniques	A
Erosion (Control or Prevention)	U
Restoration of Lands	A
Permits	A
Matters not Inconsistent	U
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A

Explanatory Remarks -

Km 178.1:

During the inspection on July 31, 2018 at Km 178.1 there is concern that the stream flowing between the entrance and the gravel pile has not been addressed as requested numerous times in the previous inspection reports.

There has been a bit of rain in the area in the last few days and the water flowing through the site is significantly more than what was viewed in the last inspection dated July 25, 2018. The stream is creating more channels over the edge of the bank of the staging area and is getting deeper along the main channel.

Department of Lands recommends that this matter be dealt with immediately to prevent further actions with legal legislations for non-compliance.

Representative Signature

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:
Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4



Date:	July 31, 2018	Permit #:	G14E002	Page No:	3
-------	---------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6

