



Telephone: 867 777-8900

Fax: 867-777-2090

January 30, 2018

GNWT Department of Infrastructure
Bag Service #1
Inuvik, NT X0E 0T0

Attention: Jahangir Hossain

File Number G14E002
Type of Operation QUARRY SITE - Existing

Location Km 235

To: Jahangir Hossain,

An inspection of the above noted operation was conducted on January 30, 2018 by Manager, Resource Management Donald Arey.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent, Dept. of Lands Beaufort Delta Region
GLWB



ENVIRONMENTAL INSPECTION REPORT

FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF January 18, 2018
 Ensure Pre and Post data are provided as per Quarry Permit Conditions.

Permittee:	GNWT Department of Infrastructure	Permit Expiry Date:	May 24, 2019
Land Use Permit No.	G14E002	Previous Inspection:	January 18, 2018
Quarrying Permit No.		Inspection Date:	January 30, 2018
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 235		
Current Stage of Operation:	Quarrying at Km 235		
Program Modifications Approved:	NIL		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Km 235				
Facilities	A				
Location as Permitted	A				
Time as Permitted	A				
Chemicals	A				
Erosion (Control or Prevention)	A				
Fuel Storage	U				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				

Explanatory Remarks -

Km 235:

During the inspection it was observed that the pit floor was cleared of snow and drilling was in progress. It was further observed at the side of the hill where the refuel tidy tank truck is parked that the hose goes down at least 10 meters to the next level and is not properly contained as per condition 26 (1)(m) Fuel Storage item 45 and 46 which states the following;

"45. The Permittee shall set up all refueling points with secondary containment.

46 The Permittee shall not allow petroleum products to spread to surrounding lands or Watercourses."

The site supervisor Wes Bergeron was advised of the matter and will have it action on. Aside from this all environmental matters was satisfactory at the time of the inspection.



ENVIRONMENTAL INSPECTION REPORT

Please ensure that secondary containment is in place and that the Pre data is provided prior to any blasting.

MATTERS FOR FOLLOW UP

Ensure Secondary containment is in place and Pre data is provided prior to blasting.

N/A

Representative Signature

[Handwritten Signature]

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:
Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





ENVIRONMENTAL INSPECTION REPORT

Figure 5

