



Telephone: 867-777-8907
Fax: 867-777-2090

July 26, 2018

GNWT Department of Infrastructure
Bag Service #1
Inuvik, NT X0E 0T0

Attention: Jahangir Hossain

File Number: G14E002
Type of Operation: QUARRY SITE - Existing
Location: Km 6 & Km 178.1

Dear Jahangir Hossain,

An inspection of the above noted operation was conducted on July 25, 2018 by Resource Management Officer II Herbert Allen and Resource Management Officer I Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC:

Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region

GLWB



ENVIRONMENTAL INSPECTION REPORT

Permittee:	GNWT Department of Infrastructure	Permit Expiry Date:	May 24, 2019
Land Use Permit No.	G14E002	Previous Inspection:	July 17, 2018
Quarrying Permit No.		Inspection Date:	July 25, 2018
Contractor:	DOI	Subcontractor:	
Location(s) Inspected:	Km 6 & Km 178.1		
Current Stage of Operation:	ongoing		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Km 178.1	Km 6			
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Erosion (Control or Prevention)	U				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Location as Permitted		A			
Time as Permitted		A			
Methods & Techniques		A			
Erosion (Control or Prevention)		A			
Restoration of Lands		A			
Permits		A			
Matters not Inconsistent		A			
Sections 12 to 19 T.L.U.R.		A			

Explanatory Remarks - Km 178.1:

During the inspection on July 25, 2018 at Km 178.1 there is still a concern that the stream flowing through the site between the entrance and the gravel pile is eroding the bank of the staging area. This stream seems to be flowing nonstop since spring freshet and one pass over the stream with a small truck created a lot of sediment flowing down the stream and it is flowing into the fish bearing river below that may trigger Department of Fisheries and Oceans involvement.

It was stated in the previous inspection reports dated May 30, 2018, July 5, 2018, July 10, 2018 and July 17, 2018 that this issue should be dealt with but nothing is done at this time.

If this matter is not dealt with as requested, Department of Lands will consider further actions with legal legislations for non-compliance.

Km 6:

During the inspection on July 25, 2018 there were no concerns observed by the inspectors at km 6 at this time.



ENVIRONMENTAL INSPECTION REPORT

At the time of the inspection there was no activity occurring at the site and the area is clean.

Representative Signature

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1, Km 178.1



Figure 2, km 178.1



Date:	July 25, 2018	Permit #:	G14E002	Page No:	3
-------	---------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Figure 3, km 178.1



Figure 4, km 178.1





ENVIRONMENTAL INSPECTION REPORT

Figure 5, km 6



Figure 6, km 6

