



Telephone: 867-777-8907
Fax: 867-777-2090

November 4, 2019

GNWT Department of Infrastructure
Bag Service #1
Inuvik, NT X0E 0T0

Attention: Michele Davies

File Number G14E002
Type of Operation QUARRY SITE - Existing
Location Km 251

Dear Michele Davies,

An inspection of the above noted operation was conducted on October 30, 2019 by Resource Management Officer II Herbert Allen and Resource Management Officer I Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC:
Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region
GLWB



ENVIRONMENTAL INSPECTION REPORT

Permittee:	GNWT Department of Infrastructure	Permit Expiry Date:	May 24, 2021
Land Use Permit No.	G14E002	Previous Inspection:	October 17, 2019
Quarrying Permit No.		Inspection Date:	October 30, 2019
Contractor:	DOI	Subcontractor:	
Location(s) Inspected:	Km 251		
Current Stage of Operation:	No work at this time		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	Km 251			
Location as Permitted	A			
Time as Permitted	A			
Equipment as Approved (Type & Size)	A			
Erosion (Control or Prevention)	A			
Chemicals	U			
Fuel Storage	A			
Matters not Inconsistent	A			

Explanatory Remarks -

Km 251:

During the inspection on October 30, 2019 at km 251 there are a few concerns observed by the inspectors.

There is oil leaks under all the loaders that are parked at the site, there is a puddle of hydraulic oil under the cone crusher and other leaks in different sections of the crusher. The rest of the site is in good order and there is no activity occurring at this time.

Please ensure these spills are cleaned up asap.

Department of Lands did receive the pre-data and please ensure the post-data is submitted to us in a timely manner.

Representative Signature

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6

