



Telephone: 867 777-8900  
Fax: 867-777-2090

August 11, 2017

Bob's Welding Ltd.  
P.O. Box 2644  
Inuvik, NT X0E 0T0

**Attention: Lyle Gully**

<b>File Number</b>	<b>G16Q004</b>
<b>Type of Operation</b>	<b>QUARRY SITE - Existing</b>
<b>Location</b>	<b>KM 251 Quarry</b>

To Lyle Gully,

An inspection of the above noted operation was conducted on August 09, 2017 by Manager, Resource Management Donald Arey and Resource Management Officer I Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey  
Manager, Resource Management  
Department of Lands  
Beaufort Delta Region

CC: GLWB



## ENVIRONMENTAL INSPECTION REPORT

### FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF July 11, 2017

July 11, 2017 Inspection

Remove unnecessary equipment and stockpiles of material.

<b>Permittee:</b>	Bob's Welding Ltd.	<b>Permit Expiry Date:</b>	May 25, 2021
<b>Land Use Permit No.</b>	G16Q004	<b>Previous Inspection:</b>	July 11, 2017
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	August 09, 2017
<b>Contractor:</b>	Bob's Welding Ltd.	<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	KM 251 Quarry		
<b>Current Stage of Operation:</b>	Ongoing		
<b>Program Modifications Approved:</b>	NIL		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Km 251				
Time as Permitted	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Facilities	A				
Chemicals	U				
Equipment as Approved (Type & Size)	A				
Permits	A				
Matters not Inconsistent	A				
Location as Permitted	A				
Methods & Techniques	A				
Fuel Storage	A				

**Explanatory Remarks -**

**Km 251:**

During the inspection it was observed that there are 12 stockpiles of crushed material that still need to be removed from the quarry. The last two inspection reports dated June 27, 2017 and July 12, 2017 requested the crushed material to be removed as this is a multi-user pit. A new permit will not be issued until all the material has been removed from the quarry. It was also observed that the burn barrel in the south-east corner of the pit has some burnt oil/fuel filters and a small pail of a hydrocarbon substance about 3/4 full near the burn barrel which needs to be removed and disposed of properly. This quarry permit, issued by the Gwich'in Land and Water Board (GLWB) in accordance with the Mackenzie Valley Resource Management Act (MVRMA) do not allow the incineration or improper storage of oil/fuel lubricants.



## ENVIRONMENTAL INSPECTION REPORT

### MATTERS FOR FOLLOW UP

Ensure the stockpiles are removed.

Ensure the metal/garbage debris and small pail of hydrocarbon is cleaned up properly.

*N/A*

\_\_\_\_\_  
Representative Signature

*[Handwritten Signature]*

\_\_\_\_\_  
Inspector's Signature

Date:	August 09, 2017	Permit #:	G16Q004	Page No:	2
-------	-----------------	-----------	---------	----------	---





## ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

**Figure 1**

**A picture of the pit with all the stockpiles.**



**Figure 2**

**The burn barrel in the south-east portion of the pit. Notice the small green pail to the left of the burn barrel and some metal debris in front.**







## ENVIRONMENTAL INSPECTION REPORT

Figure 3

Inside the burn barrel among the ashes are some oil/fuel filters and grease-gun tubes.



Figure 4

Some garbage debris scattered near the burn barrel.

