



Telephone: 867 777-8900
Fax: 867-777-2090

December 4, 2020

Bob's Welding Ltd.
P.O. Box 2644
Inuvik, NT X0E 0T0

Attention: Lyle Gully

File Number	G16Q004
Type of Operation	QUARRY SITE - Existing
Location	Km 251

To: Lyle Gully,

An inspection of the above noted operation was conducted on December 04, 2020 by Manager, Resource Management Donald Arey.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent Lands, Beaufort Delta Region
GLWB

Bag Service #1, Inuvik, NT X0E 0T0



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Bob's Welding Ltd.	Permit Expiry Date:	May 25, 2021
Land Use Permit No.	G16Q004	Previous Inspection:	November 24, 2020
Quarrying Permit No.		Inspection Date:	December 04, 2020
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 251		
Current Stage of Operation:	ongoing		
Program Modifications Approved:	New Quarry permit issued for removal of material		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	Km 251			
Location as Permitted	U			
Time as Permitted	U			
Equipment as Approved (Type & Size)	A			
Methods & Techniques	A			
Facilities	A			
Erosion (Control or Prevention)	A			
Chemicals	A			
Wildlife and Fisheries Habitat (Protection)	A			
Wastes	A			
Historical / Archaeological Sites	A			
Fuel Storage	A			
Brush Disposal	A			
Restoration of Lands	A			
Permits	A			
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A			

Explanatory Remarks -
Km 251:

An inspection was conducted to the site at Km 251 to ensure that material is being removed.

Please note that some material was removed however it is recommended that material by the north wall be removed first as other contractors need to get to their work locations provided to them, this has been previously mentioned in past inspection reports in regards to other contractors to work in the area and that this is a multi user pit/source. It is highly recommended that the materials mentioned be removed ASAP.

MATTERS FOR FOLLOW UP

Ensure material by north side wall is removed as previously indicated.

N/A

 Representative Signature

 Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1





Figure 2



Date:	December 04, 2020	Permit #:	G16Q004	Page No:	2
-------	-------------------	-----------	---------	----------	---





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

