



Telephone: 867 777-8900

Fax: 867-777-2090

July 25, 2019

Bob's Welding Ltd.
P.O. Box 2644
Inuvik, NT X0E 0T0

Attention: Lyle Gully

File Number G16Q004
Type of Operation QUARRY SITE - Existing
Location Km 251

To Lyle Gully,

An inspection of the above noted operation was conducted on July 24, 2019 by Manager, Resource Management Donald Arey.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent Lands, Beaufort Delta Region
GLWB



ENVIRONMENTAL INSPECTION REPORT

FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF June 12, 2019
 Ensure that removal of material is completed

Permittee:	Bob's Welding Ltd.	Permit Expiry Date:	May 25, 2021
Land Use Permit No.	G16Q004	Previous Inspection:	June 12, 2019
Quarrying Permit No.		Inspection Date:	July 24, 2019
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 251		
Current Stage of Operation:	material to be removed		
Program Modifications Approved:	NIL		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	Km 251			
Location as Permitted	A			
Time as Permitted	A			
Equipment as Approved (Type & Size)	A			
Methods & Techniques	A			
Facilities	A			
Erosion (Control or Prevention)	A			
Chemicals	A			
Wastes	A			
Fuel Storage	A			

Explanatory Remarks -
 Km 251:
 Please note that your quarry permit that a letter for refund for quarry permit 2018QP0021 has been sent to headquarters for the requisition for remaining 5882 cm as requested as per the survey you had provided in volumes removed.
 Please ensure that stockpiles are to be removed from the location as km 251 is a multi user pit. It is understood that Bobs welding will be working under DOI's quarry permit during this work your stock piled material should be removed from the site as previously mention.

MATTERS FOR FOLLOW UP

Stock piled material to be removed from site.

N/A
 Representative Signature

[Signature]
 Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

