



Telephone: 867-777-8907
Fax: 867-777-2090

November 16, 2020

Bob's Welding Ltd.
P.O. Box 2644
Inuvik, NT X0E 0T0

Attention: Lyle Gully

File Number G16Q004
Type of Operation QUARRY SITE - Existing
Location Km 251

Dear Lyle Gully,

An inspection of the above noted operation was conducted on November 12, 2020 by Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC:
Dan Carmichael, Regional Superintendent Lands, Beaufort Delta Region
GLWB

Bag Service 1, Inuvik, NT X0E 0T0



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Bob's Welding Ltd.	Permit Expiry Date:	May 25, 2021
Land Use Permit No.	G16Q004	Previous Inspection:	October 19, 2020
Quarrying Permit No.		Inspection Date:	November 12, 2020
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 251		
Current Stage of Operation:	On-going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Km 251				
Chemicals	A				
Wastes	A				
Fuel Storage	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				

Explanatory Remarks -

Km 251:

During the inspection on November 12, 2020 at the km 251 pit, there were no concerns observed by the inspector.

It appears that work has just begun to start removing the material from the site, there were a few trucks hauling material away.

Please be advised that all stock piled material must be removed from the site before the quarry volumes are to be increased and new blasting can take place.

Representative Signature

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:
Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

