



Telephone: 867 777-8900

Fax: 867-777-2090

September 6, 2018

Bob's Welding Ltd.
P.O. Box 2644
Inuvik, NT X0E 0T0

Attention: Lyle Gully

File Number G16Q004
Type of Operation QUARRY SITE - Existing
Location KM 251 Quarry

Dear Lyle Gully,

An inspection of the above noted operation was conducted on September 05, 2018 by Manager, Resource Management Donald Arey and Resource Management Officer I Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867 777-8900.

Sincerely,

Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC:
Dan Carmicheal, Regional Superintendent, Department of Lands, Beaufort Delta Region
Gwich'in Land and Water Board



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Bob's Welding Ltd.	Permit Expiry Date:	May 25, 2021
Land Use Permit No.	G16Q004	Previous Inspection:	July 17, 2018
Quarrying Permit No.		Inspection Date:	September 05, 2018
Contractor:		Subcontractor:	
Location(s) Inspected:	KM 251 Quarry		
Current Stage of Operation:	On-going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	Km 251			
Location as Permitted	A			
Time as Permitted	A			
Equipment as Approved (Type & Size)	A			
Methods & Techniques	A			
Facilities	A			
Erosion (Control or Prevention)	A			
Chemicals	A			
Wastes	A			
Fuel Storage	A			
Matters not Inconsistent	A			
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A			

Explanatory Remarks -

Km 251:

During the inspection it was observed that the contractor had the crusher and equipment setup, but no excavation or crushing was occurring at the time.
Please ensure that the Post-survey data is submitted to the Department of Lands within 60 days of completion of the operation.

N/A

Representative Signature

[Signature]

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

The crusher parked in the middle of the pit floor.



Figure 2

A general photo overlooking the entire pit.





ENVIRONMENTAL INSPECTION REPORT

Figure 3
Some of the equipment used for the operation of the pit.



Figure 4
An excavator sitting amongst the blast material.





ENVIRONMENTAL INSPECTION REPORT

Figure 5

Some of the blast material sloped towards the crusher, ready for processing.

