



Telephone: 867-777-8907
Fax: 867-777-2090

September 15, 2017

L.J.'s Septic Services & Contracting Ltd.
P.O. Box 151
Fort McPherson, NT X0E 0J0

Attention: Leslie J Blake

File Number	G17Q005
Type of Operation	QUARRY SITE - Existing
Location	Km 66 on the Dempster Highway

Dear Leslie J Blake,

An inspection of the above noted operation was conducted on September 07, 2017 by Resource Management Officer II Herbert Allen and Manager, Resource Management Donald Arey.

Enclosed is a copy of the Environmental Inspection Report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-777-8907.

Sincerely,


Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC: Dan Carmichael, Superintendent, Department of Lands. Beaufort Delta Region

GLWB

ENVIRONMENTAL INSPECTION REPORT

Permittee:	L.J.'s Septic Services & Contracting Ltd.	Permit Expiry Date:	March 28, 2022
Land Use Permit No.	G17Q005	Previous Inspection:	August 24, 2017
Quarrying Permit No.		Inspection Date:	September 07, 2017
Contractor:	L.J.'s Septic Services & Contracting Ltd.	Subcontractor:	
Location(s) Inspected:	Km 66 on the Dempster Highway		
Current Stage of Operation:	hauling crushed gravel from the site		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected
	Km 66 Stock pile site
Chemicals	A
Location as Permitted	A
Erosion (Control or Prevention)	A
Permits	A
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A
Methods & Techniques	A
Time as Permitted	A
Equipment as Approved (Type & Size)	A

Explanatory Remarks -

Km 66 Stock pile site:

During the inspection on September 7, 2017 there is no concerns observed by the inspectors.

L.J.'s crew were busy hauling away the crushed gravel from the site for the road maintenance on the Dempster Highway. The rock crushers were removed from the site except for one, it is parked at the back of the gravel pile on the east side.

The garbage from around the area was gathered up and placed in piles at the site and some garbage was put in a sea can. The oil that was in the puddle by the crusher indicated in the last inspection report was cleaned up from the area.

Please ensure there is no oil leaks on the equipment that is parked at the site and all the garbage and scrap material is removed before the snow falls.



Representative Signature



Inspector's Signature

ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Gravel truck in line for load of gravel



Figure 2

One rock crusher remaining at the site





ENVIRONMENTAL INSPECTION REPORT

Figure 3
Garbage on site



Figure 4
garbage in sea can





ENVIRONMENTAL INSPECTION REPORT

Figure 5

Oil cleaned up from puddle



Figure 6

Equipment on site

