



Telephone: 867-777-8907  
Fax: 867-777-2090

July 16, 2019

GNWT Department of Infrastructure  
Bag Service #1  
Inuvik, NT X0E 0T0

**Attention: Mohammad Hossain**

**File Number** G17Q007  
**Type of Operation** QUARRY SITE - Existing  
**Location** Km 66

Dear Mohammad Hossain,

An inspection of the above noted operation was conducted on July 10, 2019 by Resource Management Officer II Herbert Allen and Resource Management Officer I Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen  
Resource Management Officer II  
Department of Lands  
Beaufort Delta Region

CC:  
Donald Arey Acting Superintendent, Department of Lands, Beaufort Delta Region

GLWB



## ENVIRONMENTAL INSPECTION REPORT

|  |                                   |                             |                  |
|--|-----------------------------------|-----------------------------|------------------|
| <b>Permittee:</b>                      | GNWT Department of Infrastructure | <b>Permit Expiry Date:</b>  |                  |
| <b>Land Use Permit No.</b>             | G17Q007                           | <b>Previous Inspection:</b> | January 17, 2018 |
| <b>Quarrying Permit No.</b>            |                                   | <b>Inspection Date:</b>     | July 10, 2019    |
| <b>Contractor:</b>                     | DOI                               | <b>Subcontractor:</b>       |                  |
| <b>Location(s) Inspected:</b>          | Km 66                             |                             |                  |
| <b>Current Stage of Operation:</b>     |                                   |                             |                  |
| <b>Program Modifications Approved:</b> |                                   |                             |                  |

**Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected**

| Operating Condition                         | Aspect Inspected |  |  |  |  |
|---|------------------|--|--|--|--|
|   | <b>Km 66</b>     |  |  |  |  |
| Location as Permitted                       | A                |  |  |  |  |
| Time as Permitted                           | A                |  |  |  |  |
| Equipment as Approved (Type & Size)         | A                |  |  |  |  |
| Methods & Techniques                        | A                |  |  |  |  |
| Erosion (Control or Prevention)             | A                |  |  |  |  |
| Wildlife and Fisheries Habitat (Protection) | A                |  |  |  |  |
| Brush Disposal                              | A                |  |  |  |  |
| Restoration of Lands                        | A                |  |  |  |  |
| Permits                                     | A                |  |  |  |  |
| Matters not Inconsistent                    | A                |  |  |  |  |
| Sections 8 to 12 / 14 to 16 M.V.L.U.R.      | A                |  |  |  |  |

**Explanatory Remarks -**

Km 66:

During the inspection at Km 66 on July 10, 2019 there were no concerns observed by the inspectors.

There was no activity at the site during the inspection and the site looked in good order.

\_\_\_\_\_  
Representative Signature

\_\_\_\_\_  
Inspector's Signature



# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

**Figure 1**



**Figure 2**







# ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

