



Telephone: 867-777-8907

Fax: 867-777-2090

December 6, 2018

GNWT Department of Infrastructure
Bag Service #1
Inuvik, NT X0E 0T0

Attention: **Mohammad Hossain**

File Number G18Q003
Type of Operation QUARRY SITE - Existing
Location Frog Creek gravel source

Dear Mohammad Hossain,

An inspection of the above noted operation was conducted on December 05, 2018 by Resource Management Officer II Herbert Allen and Resource Management Officer I Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC:

Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region

GLWB

GTC



ENVIRONMENTAL INSPECTION REPORT

| | | | |
|--|---|-----------------------------|-------------------|
| Permittee: | GNWT Department of Infrastructure | Permit Expiry Date: | July 23, 2023 |
| Land Use Permit No. | G18Q003 | Previous Inspection: | October 24, 2018 |
| Quarrying Permit No. | | Inspection Date: | December 05, 2018 |
| Contractor: | L.J.'s Septic Services & Contracting Ltd. | Subcontractor: | |
| Location(s) Inspected: | Frog Creek gravel source | | |
| Current Stage of Operation: | no work occurring at this time | | |
| Program Modifications Approved: | | | |

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

| Operating Condition | Aspect Inspected | | | | |
|---|------------------|--|--|--|--|
| | Km 126 | | | | |
| Equipment as Approved (Type & Size) | A | | | | |
| Methods & Techniques | A | | | | |
| Erosion (Control or Prevention) | A | | | | |
| Chemicals | U | | | | |
| Wildlife and Fisheries Habitat (Protection) | A | | | | |
| Fuel Storage | A | | | | |
| Brush Disposal | A | | | | |
| Restoration of Lands | A | | | | |
| Location as Permitted | A | | | | |
| Time as Permitted | A | | | | |

Explanatory Remarks -

Km 126:

During the inspection at Frog Creek there was one concern observed by the inspectors.

There was a small oil leak trail near the excavator which was about 3 meters long.

The road to the pit was plowed but there is no activity occurring at the site during the inspection. The gravel pile by the crushers has been removed from the site since the last inspection.

Representative Signature

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Where the last gravel pile was near the crushers



Figure 2

Crushers





ENVIRONMENTAL INSPECTION REPORT

Figure 3
Excavator at the site



Figure 4
Small oil trail

