



Telephone: 867-777-8907

Fax: 867-777-2090

October 12, 2018

GNWT Department of Infrastructure
Bag Service #1
Inuvik, NT XOE 0T0

Attention: **Jahangir Hossain**

File Number G18Q003
Type of Operation QUARRY SITE - Existing
Location Km 126

Dear Jahangir Hossain,

An inspection of the above noted operation was conducted on October 11, 2018 by Resource Management Officer II Herbert Allen and Resource Management Officer I Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC:

Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region
GLWB



ENVIRONMENTAL INSPECTION REPORT

Permittee:	GNWT Department of Infrastructure	Permit Expiry Date:	July 23, 2023
Land Use Permit No.	G18Q003	Previous Inspection:	New
Quarrying Permit No.		Inspection Date:	October 11, 2018
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 126		
Current Stage of Operation:	Existing Quarry		
Program Modifications Approved:	GTC Authorization # GTC18Q001		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	Km 126			
Location as Permitted	A			
Time as Permitted	A			
Equipment as Approved (Type & Size)	A			
Methods & Techniques	A			
Erosion (Control or Prevention)	A			
Chemicals	U			
Wildlife and Fisheries Habitat (Protection)	A			
Fuel Storage	A			
Brush Disposal	A			
Restoration of Lands	A			

Explanatory Remarks -
Km 126:

During the inspection on October 11, 2018 there was one concern observed by the inspectors.

There is an oil leak under one of the rock crushers at the south end of the pit that should be cleaned up before it is covered with snow. The rest of the site looks in order but there is a lot of snow cover over the work site at this time.

There was a concern brought to our attention from GTC regarding salvageable trees not being accessible at the site. It appears that some of the trees have been piled with in the pit when we were there to conducted the inspection.

Representative Signature

Inspector's Signature

Date:	October 11, 2018	Permit #:	G18Q003	Page No:	1
-------	------------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Oil under the crusher



Figure 2

Oil spill is under the closest crusher in this picture





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6

