



Telephone: 867-777-8907
Fax: 867-777-2090

January 28, 2021

GNWT Department of Infrastructure
Bag Service #1, 106 Veterans Way
Inuvik, NT X0E 0T0

Attention: Mosiul Alam

File Number	G20H006
Type of Operation	CAMPS
Location	James Creek Km 14.2

Dear Mosiul Alam,

An inspection of the above noted operation was conducted on January 27, 2021 by Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC:

Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region

GLWB

Bag Service 1, Inuvik, NT X0E 0T0



ENVIRONMENTAL INSPECTION REPORT

Permittee:	GNWT Department of Infrastructure	Permit Expiry Date:	August 05, 2021
Land Use Permit No.	G20H006	Previous Inspection:	January 12, 2021
Quarrying Permit No.	68	Inspection Date:	January 27, 2021
Contractor:	L.J.'s Septic Services & Contracting Ltd.	Subcontractor:	
Location(s) Inspected:	James Creek Km 14.2		
Current Stage of Operation:	on-going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	James Creek Km 14.2				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Fuel Storage	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

Explanatory Remarks -

James Creek Km 14.2:

During the inspection on January 27, 2021 at the James Creek maintenance camp there were no concerns observed by the inspectors.

The site looks in good order.

Representative Signature

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6

