



Deh Cho Region
P.O. Box 150
Fort Simpson, NT. X0E 0N0

Telephone: 867-695-2626 ext.206
Fax: 867-695-2615

December 2, 2016

GNWT - Department of Transportation
P.O. Box 1320
Yellowknife, NT X1A 2L9

Attention: Binay Yadav

File Number	MV2016E0006
Type of Operation	HWY MAINTENANCE & OPERATIONS
Location	Non-active Km 436.5 Quarry

Dear Binay Yadav ,

An inspection of the above noted operation was conducted on October 26, 2016 by Resource Management Officer II Kyle Christiansen and Manager, Resource Management Jarret Hardisty.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-695-2626 ext.206.

Sincerely,

Kyle Christiansen
Resource Management Officer II
Department of Lands
Deh Cho Region

CC:

Permits – MVLWB

Jarret Hardisty – Manager, Resource Management, GNWT Lands, Deh Cho Region

Laurie Nadia – Regional Superintendent, GNWT Lands, Deh Cho Region

Dustin Dewar – Regional Highway Manager, GNWT Transportation



ENVIRONMENTAL INSPECTION REPORT

Permittee:	GNWT - Department of Transportation	Permit Expiry Date:	June 08, 2021
Land Use Permit No.	MV2016E0006	Previous Inspection:	October 26, 2016
Quarrying Permit No.	14/47, 15/14, 15/28, 16/12, 16/29	Inspection Date:	October 26, 2016
Contractor:		Subcontractor:	
Location(s) Inspected:	Non-active Km 436.5 Quarry		
Current Stage of Operation:	Complete		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Asphalt clean up				
Location as Permitted	A				
Time as Permitted	A				
Restoration of Lands	A				

Explanatory Remarks -

Asphalt clean up:

Inspectors from the Department of Lands inspected the Km 436.5 non-active quarry to follow up on a request to clean up the liquid asphalt that was found on the ground surface.

The locations identified in the previous inspection were addressed and appeared to be cleaned up. However there was a snowfall event prior to the inspection. The asphalt tanker trailer that was stored on site and the asphalt covered hose were removed from the area.

At this time inspectors have no concerns with the Km 436.5 asphalt clean up. Inspectors will follow up with an inspection next year after the snow has melted.



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Area near access road where asphalt was cleaned up.



Figure 2

Figure 1 prior to clean up.





ENVIRONMENTAL INSPECTION REPORT

Figure 3

Location where asphalt covered hose was found. Location is now cleaned and hose was removed.



Figure 4

Figure 3 prior to clean up.





ENVIRONMENTAL INSPECTION REPORT

Figure 5

Another location where asphalt was located and now cleaned up.



Figure 6

Figure 5 prior to clean up.





ENVIRONMENTAL INSPECTION REPORT

Figure 7

Final location where asphalt was found and is now cleaned up.



Figure 8

Figure 7 prior to clean up.

