



Telephone: 867 874-6994

Fax: 867 874-2460

August 15, 2018

Rowe's Construction
25 Studney Drive
Hay River, NT X0E 0R9

Attention: Florian Mandsfeld

File Number MV2018Q0003
Type of Operation QUARRY SITE - New
Location Km 100, NWT Highway No. 1

Dear Mr. Mandsfeld,

An inspection of the above noted operation was conducted on June 26, 2018 by Resource Management Officers Jayda Robillard and Norm McCowan.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 874-6994.

Sincerely,

ORIGINAL SIGNED

Jayda Robillard
Resource Management Officer II
Department of Lands
South Slave Region

CC: Mackenzie Valley Land and Water Board
Regional Superintendent, South Slave – GNWT Dept of Lands
Land Use Advisor, North Slave – GNWT Dept of Lands



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Rowe's Construction (851791 NWT Ltd)	Permit Expiry Date:	March 28, 2023
Land Use Permit No.	MV2018Q0003	Previous Inspection:	New
Quarrying Permit No.	18/0007	Inspection Date:	June 26, 2018
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 100, NWT Highway No. 1		
Current Stage of Operation:	Permittee is clearing the wooded area on the west side of the existing clearing in preparation for quarrying activity.		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Pit				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Historical / Archaeological Sites	A				
Fuel Storage	U (35)				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				

Explanatory Remarks -

A pre-inspection of the expanded land use area was conducted on May 18, 2018 with Mr. Florian Mandsfield and Inspectors Norm McCowan and Jayda Robillard. During the pre-inspection Mr. Mandsfield flagged the boundaries of the expanded land use area.

At the time of the inspection the Permittee had finished logging an area approximately 220m x 105m on the west side of the land use area in preparation for expanding the existing quarry site. Salvaged timber has been decked into three piles on the north edge of the clearing. Overburden is being stripped and stored on the north side of the existing clearing (east side of land use area).

A dump truck was parked on the west side of the clearing, it was noted that there was no drip tray under the equipment (**Condition 35**)



ENVIRONMENTAL INSPECTION REPORT

A dozer was parked on site with no drip tray underneath. **Note that Condition 35 of your LUP requires "All equipment that may be parked for two hours or more, shall have a haz-mat/drip tray under it or be sufficiently diapered. Leaky equipment shall be repaired immediately."**

The existing quarry site has several stockpiles of processed material. Granular material has been removed from the stockpiles this season under the authority of quarry permit #2018QP0007.

Representative Signature

Original signed by Jayda Robillard

Inspector's Signature

Date:	June 26, 2018	Permit #:	MV2018Q0003	Page No:	2
-------	---------------	-----------	-------------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

West side of the land use area. Dump truck parked along access road.



Figure 2

Dump truck requires a drip tray.



Figure 3

Overburden is being stripped from the new clearing on the west side.



Figure 4

Overburden is being stripped from the new clearing on the west side.



Figure 5

Salvaged timber is decked for public use.



Figure 6

Second pile of salvaged timber.





ENVIRONMENTAL INSPECTION REPORT

Figure 7

East side of the land use area at the existing quarry site.



Figure 8

Overburden is being stored on the north side of the existing quarry site.



Figure 9

Dozer parked in the existing quarry.



Figure 10

Dozer requires a drip tray.

