



Sahtu Region  
P.O. Box 126 - 31 Mackenzie Rd.  
Norman Wells, NT, X0E 0V0

Telephone: 867 587-7205  
Fax: 867-587-2928

March 18, 2015

Suncor Energy Inc.  
P.O. Box 2844  
150-6 Ave S.W.  
Calgary, NT T2P 3E3

**Attn: John Kerkhoven**

**RE: Land Use Permit S14A-006  
Water Access, Winter Access Road, M-47 Well pad**

Dear Mr. Kerkhoven,

An inspection of the above noted operation was conducted on January 26, 2015 by Manager of Resource Management Katherine Ades.

Enclosed is a copy of the Environmental Inspection Report. All aspects of your lease are satisfactory at the time of this inspection.

If you have any questions, please contact me at 867 587-7205.

Sincerely,

Katherine Ades  
Manager, Resource Management  
GNWT – Department of Lands, Sahtu Region

Cc:

Stephen Deschene – Regional Superintendent, GNWT Lands, Sahtu Region  
Bakhtiyor Mukhammadiev – Regulatory Specialist, SLWB  
Norman McCowan – Manager of Resource Management, GNWT Lands, South Slave Region  
Cliff Seibel – Logistics Project Lead, Suncor Energy



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	Suncor Energy Inc.	<b>Permit Expiry Date:</b>	November 16, 2019
<b>Land Use Permit No.</b>	S14A-006	<b>Previous Inspection:</b>	January 26, 2015
<b>Quarrying Permit No.</b>	N/A	<b>Inspection Date:</b>	March 06, 2015
<b>Contractor:</b>	Suncor Energy Inc.	<b>Subcontractor:</b>	N/A
<b>Location(s) Inspected:</b>	Water Access, Access Road, M-47 Well pad		
<b>Current Stage of Operation:</b>	Re-suspension complete. Equipment and materials removed.		
<b>Program Modifications Approved:</b>	None		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	Water Access	Winter Access Road	M-47 Well Pad	
Brush Disposal	N/A	A	A	
Chemicals	N/A	A	A	
Ecological Resources	A	A	A	
Equipment as Approved (Type & Size)	A	A	A	
Erosion (Control or Prevention)	A	A	A	
Facilities	A	A	A	
Fuel Storage	N/A	N/A	A	
Historical / Archaeological Sites	N/A	N/A	N/A	
Location as Permitted	A	A	A	
Methods & Techniques	A	A	A	
Permits	A	A	A	
Restoration of Lands	A	N/I	N/I	
Time as Permitted	A	A	A	
Wastes	A	A	A	
Wildlife and Fisheries Habitat (Protection)	A	A	A	

**Explanatory Remarks –**

Activities on site are complete. There are no concerns for the water access pad on Colville Lake (Figure 1).

From the air, no signs of rutting, erosion, or spills were noted along the winter access road.

All equipment, materials, garbage, etc. had been removed from the M-47 well pad at the time of inspection. The wood planks beneath the well have been replaced and the old ones removed. Due to a layer of newly fallen snow, no signs of spills or garbage were visible at the time of inspection.

\_\_\_\_\_  
Representative Signature

\_\_\_\_\_  
Inspector's Signature

# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

## Figure 1

Aerial view of the water access site.



## Figure 2

Aerial view of M-47 well pad.



## Figure 3

Re-suspended well cap on M-47 well pad.

