



Telephone: 867 777-8900

Fax: 867-777-2090

September 20, 2017

Chinook Energy Inc.
Suite 1000, 517-10th Avenue SW
Calgary, AB T2R 0A8

Attention: **Darren Tomecek**

File Number G02A011
Type of Operation OIL AND GAS DRILLING - WELLSITE
Location Tree River C-36

To: Darren Tomecek,

An inspection of the above noted operation was conducted on September 19, 2017 by Manager, Resource Management Donald Arey and Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent, Beaufort Delta Region
GLWB



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Chinook Energy Inc.	Permit Expiry Date:	December 31, 2005
Land Use Permit No.	G02A011	Previous Inspection:	September 21, 2016
Quarrying Permit No.		Inspection Date:	September 19, 2017
Contractor:		Subcontractor:	
Location(s) Inspected:	Tree River C-36		
Current Stage of Operation:	reclamation completed		
Program Modifications Approved:	NIL		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Tree River C-36				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Fuel Storage	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

Explanatory Remarks -
Tree River C-36:

During this inspection it was observed that no ponding was evident, the sump cap was solid with no visible signs of subsidence. The sight looks good at this time and vegetation cover is at least 80 percent.

Please note that the previous inspection report dated Sept. 23, 2016 requested a updated sample report to ensure that there was no leakage from the sump, this has not yet been provided to our office.

It is requested that a sump assessment be provided as previously requested to ensure on the sumps integrity prior to any recommendations for closure..



ENVIRONMENTAL INSPECTION REPORT

MATTERS FOR FOLLOW UP

a sump assessment be provided as previously requested to ensure on the sumps integrity prior to any recommendations for closure..

N/A

Representative Signature

[Handwritten Signature]

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6



Date:	September 19, 2017	Permit #:	G02A011	Page No:	5
-------	--------------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Figure 7



Date:	September 19, 2017	Permit #:	G02A011	Page No:	6
-------	--------------------	-----------	---------	----------	---