



Telephone: 867 777-8900  
Fax: 867-777-2090

July 14, 2017

L.J.'s Septic Services & Contracting Ltd.  
P.O. Box 151  
Fort McPherson, NT X0E 0J0

Attention: Leslie J Blake

received  
19.7.17

**File Number** G16Q001  
**Type of Operation** QUARRY SITE - Existing  
**Location** Frog Creek

To: Leslie J Blake,

An inspection of the above noted operation was conducted on July 12, 2017 by Manager, Resource Management Donald Arey and Resource Management Officer I Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the general comments section of this report.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey  
Manager, Resource Management  
Department of Lands  
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent, Beaufort Delta Region  
GLWB  
GTC



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	L.J.'s Septic Services & Contracting Ltd.	<b>Permit Expiry Date:</b>	March 14, 2021
<b>Land Use Permit No.</b>	G16Q001	<b>Previous Inspection:</b>	April 26, 2017
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	July 12, 2017
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	Frog Creek		
<b>Current Stage of Operation:</b>	Completed		
<b>Program Modifications Approved:</b>	NIL		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	<b>Frog Creek Quarry</b>				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Permits	A				
Matters not Inconsistent	A				
Restoration of Lands	A				
Erosion (Control or Prevention)	A				

**Explanatory Remarks -**

**Frog Creek Quarry:**

Work at the location is completed and materials removed, the site during the inspection looks all satisfactory with no concerns for reclamation the pit floor and walls are satisfactory.

N/A

\_\_\_\_\_  
Representative Signature

\_\_\_\_\_  
Inspector's Signature



# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2







# ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

