



Telephone: 867 777-8900

Fax: 867-777-2090

August 29, 2016

RECEIVED
SEP 06 2016

Bob's Welding Ltd.
P.O. Box 2644
Inuvik, NT X0E 0T0

Attention: Lyle Gully

File Number G16Q004
Type of Operation QUARRY SITE - Existing
Location Km 251

To: Lyle Gully,

An inspection of the above noted operation was conducted on August 26, 2016 by Manager, Resource Management Donald Arey and Resource Management Officer I Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC: **GLWB**
Conrad Baetz, Regional Superintendent, Beaufort Delta Region

ENVIRONMENTAL INSPECTION REPORT

FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF May 27, 2016

Ensure previous blast material is being removed.

Permittee:	Bob's Welding Ltd.	Permit Expiry Date:	May 25, 2021
Land Use Permit No.	G16Q004	Previous Inspection:	May 27, 2016
Quarrying Permit No.		Inspection Date:	August 26, 2016
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 251		
Current Stage of Operation:	on going		
Program Modifications Approved:	New Quarry Permit was issued for 15000 cubic meters under a condition that no drilling or blasting will occur until all previously blasted material was removed.		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Km 251				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Fuel Storage	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Facilities	A				
Chemicals	A				

Explanatory Remarks -

Km 251:

During the inspection it was observed that work is currently still being done with the removal of previously quarried material. Material from the benches were removed from last inspection report dated May 30 2016. No concerns was observed during this inspection, however it should be still reminded that no drilling or blasting shall occur until previously quarried material is removed.

MATTERS FOR FOLLOW UP

monitor removal of material

N/A

Representative Signature



Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Pit floor view of bench



Figure 2

view at end of pit





ENVIRONMENTAL INSPECTION REPORT

Figure 3
view at end of pit



Figure 4
view at end of pit

