



Telephone: 867 777-8900

Fax: 867-777-2090

January 19, 2021

Bob's Welding Ltd.  
P.O. Box 2644  
Inuvik, NT X0E 0T0

**Attention: Lyle Gully**

**File Number** G16Q004  
**Type of Operation** QUARRY SITE - Existing  
**Location** Km 251 Dempster Highway

To: Lyle Gully,

An inspection of the above noted operation was conducted on January 19, 2021 by Manager, Resource Management Donald Arey and Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey  
Manager, Resource Management  
Department of Lands  
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent Lands, Beaufort Delta Region  
GLWB

Bag Service #1, Inuvik, NT X0E 0T0



## ENVIRONMENTAL INSPECTION REPORT

**FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF December 04, 2020**

Ensure material by north side wall is removed as previously indicated.

<b>Permittee:</b>	Bob's Welding Ltd.	<b>Permit Expiry Date:</b>	May 25, 2021
<b>Land Use Permit No.</b>	G16Q004	<b>Previous Inspection:</b>	December 04, 2020
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	January 19, 2021
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	Km 251 Dempster Highway		
<b>Current Stage of Operation:</b>	ongoing		
<b>Program Modifications Approved:</b>	QP for removal of stock piles only		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	Km 251			
Location as Permitted	U			
Time as Permitted	U			
Equipment as Approved (Type & Size)	A			
Methods & Techniques	A			
Facilities	A			
Erosion (Control or Prevention)	A			
Chemicals	A			
Wildlife and Fisheries Habitat (Protection)	A			
Wastes	A			
Historical / Archaeological Sites	A			
Fuel Storage	A			
Brush Disposal	A			
Restoration of Lands	A			
Permits	A			
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A			

**Explanatory Remarks -**

**Km 251:**

It is evident that past requests for removal of material to the north side wall were not followed, attached images from Dec 4, 2020 inspection requested the material on the north wall be removed ASAP as another contractor will be going into do some work, since this Dec. 04 inspection these materials were not touched at all.

During this inspection it was observed that material from the central area of the pit was removed, this is a good start however, you are again reminded that this source is a multi user source and work location are to be adhered to.

The main concern observed again is the material stock piled at the north side of the source



### ENVIRONMENTAL INSPECTION REPORT

that was previously requested during the Dec 04 2020 inspection to have them removed as they are blocking access to work location for another permit holder.

The Department of Lands is willing to work out solutions for issuing a new quarry permit, however material to the Northside wall are to be removed to another location. One aspect is to have materials to the south area where the storage shed is located. however this will be determined on removal of requested material.

#### MATTERS FOR FOLLOW UP

Materials to the North side wall are to be removed.

*N/A*

Representative Signature

*[Handwritten Signature]*

Inspector's Signature

Date:	January 19, 2021	Permit #:	G16Q004	Page No:	2
-------	------------------	-----------	---------	----------	---



# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:


**Figure 1**

**Dec. 04, 2020 image and requested for removal.**



**Figure 2**

**Dec. 04, 2020 image and requested for removal.**



Date:	January 19, 2021	Permit #:	G16Q004	Page No:	3
-------	------------------	-----------	---------	----------	---



# ENVIRONMENTAL INSPECTION REPORT


**Figure 3**

**Dec. 04, 2020 image and requested for removal.**



**Figure 4**

**Dec. 04, 2020 image and requested for removal.**





## ENVIRONMENTAL INSPECTION REPORT


**Figure 5**

**Central material removed**



**Figure 6**

**Central material removed**





## ENVIRONMENTAL INSPECTION REPORT

**Figure 7**

**Dec. 04, 2020 requested for removal Jan 19, 2021 material still blocking another permit holder access**



**Figure 8**

**Dec. 04, 2020 requested for removal Jan 19, 2021 material still blocking another permit holder access**





## ENVIRONMENTAL INSPECTION REPORT

**Figure 9**

**Dec. 04, 2020 requested for removal Jan 19, 2021 material still on site.**



**Figure 10**

**Dec. 04, 2020 requested for removal Jan 19, 2021 material still on site.**







## ENVIRONMENTAL INSPECTION REPORT

**Figure 11**

**Dec. 04, 2020 requested for removal Jan 19, 2021 material still on site.**

