



Telephone: 867 777-8900

Fax: 867-777-2090

June 14, 2022

Bob's Welding Ltd.  
P.O. Box 2644  
Inuvik, NT X0E 0T0

**Attention: Bob Gully**

<b>File Number</b>	<b>G16Q004</b>
<b>Type of Operation</b>	<b>QUARRY SITE - Existing</b>
<b>Location</b>	<b>Km 251</b>

To: Bob Gully,

An inspection of the above noted operation was conducted on June 13, 2022 by Manager, Resource Management Donald Arey and Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.


If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey  
Manager, Resource Management  
Department of Lands  
Beaufort Delta Region

CC: GLWB

Bag Service #1, Inuvik, NT X0E 0T0



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	Bob's Welding Ltd.	<b>Permit Expiry Date:</b>	May 25, 2021
<b>Land Use Permit No.</b>	G16Q004	<b>Previous Inspection:</b>	November 03, 2021
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	June 13, 2022
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	Km 251		
<b>Current Stage of Operation:</b>	2021QP0005		
<b>Program Modifications Approved:</b>	NIL		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	<b>Km 251</b>				
Location as Permitted	A				
Time as Permitted	U				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wastes	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

Explanatory Remarks -

Km 251:

During the inspection it was observed that there are a number of spills on site although this is a multi-user site it is the proponents responsibility to ensure equipment are maintained and leaking equipment are to be repaired immediately. Further observed that material is being stock piled at the site on the northern side of the pit floor. Proponent is aware that there is to be no stock piles at site and this material is to be removed from site .

Please ensure that the material is removed from site.

### **MATTERS FOR FOLLOW UP**

Stock Piles to be removed.

N/A

Representative Signature

Inspector's Signature

Date:	June 13, 2022	Permit #:	G16Q004	Page No:	1
-------	---------------	-----------	---------	----------	---



# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

**Figure 1**



**Figure 2**





# ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





# ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6





# ENVIRONMENTAL INSPECTION REPORT

Figure 7



Figure 8





# ENVIRONMENTAL INSPECTION REPORT

Figure 9

