



Telephone: 867-777-8907
Fax: 867-777-2090

September 17, 2021

Bob's Welding Ltd.
P.O. Box 2644
Inuvik, NT X0E 0T0

Attention: Bob Gully

File Number	G16Q004
Type of Operation	QUARRY SITE - Existing
Location	Km 251

Dear Bob Gully,

An inspection of the above noted operation was conducted on September 16, 2021 by Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC:

Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region
GLWB

Bag Service 1, Inuvik, NT X0E 0T0



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Bob's Welding Ltd.	Permit Expiry Date:	May 25, 2021
Land Use Permit No.	G16Q004	Previous Inspection:	July 13, 2021
Quarrying Permit No.		Inspection Date:	September 16, 2021
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 251		
Current Stage of Operation:	On-going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected
	Km 251
Location as Permitted	A
Time as Permitted	A
Equipment as Approved (Type & Size)	A
Methods & Techniques	A
Facilities	A
Erosion (Control or Prevention)	A
Chemicals	U
Wastes	A
Brush Disposal	A
Restoration of Lands	A
Permits	A
Matters not Inconsistent	U
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A

Explanatory Remarks -

Km 251:

During the inspection at Km 251 quarry on September 16, 2021 there is a couple of concerns that were observed by the inspector.

There is an oil spill under the 980 loader that is closest the back wall of the pit. There are spill trays at the site but not being used. There is still a lot of material along the walls of the pit that needs to be removed from the site and equipment should not be blocking anyone else's work area.

In a June 23, 2021 inspection report Donald Arey requested a pre and post data from a May 19th 2021 blast and we have not yet received the data.

Representative Signature

Inspector's Signature

Date:	September 16, 2021	Permit #:	G16Q004	Page No:	1
-------	--------------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:
Figure 1



Figure 2
The loader with the spill under it





ENVIRONMENTAL INSPECTION REPORT

Figure 3




Figure 4





ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6

