



Telephone: 867-777-8907
Fax: 867-777-2090

August 11, 2021

GNWT Department of Infrastructure
Bag Service #1
Inuvik, NT XOE OTO

Attention: Mosiul Alam

File Number G17Q007
Type of Operation QUARRY SITE - Existing
Location Km 66

Dear Mosiul Alam,

An inspection of the above noted operation was conducted on August 10, 2021 by Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC:
Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region

GLWB

Bag Service 1, Inuvik, NT XOE OTO

ENVIRONMENTAL INSPECTION REPORT

| | | | |
|--|-----------------------------------|-----------------------------|------------------|
| Permittee: | GNWT Department of Infrastructure | Permit Expiry Date: | January 08, 2023 |
| Land Use Permit No. | G17Q007 | Previous Inspection: | July 13, 2021 |
| Quarrying Permit No. | | Inspection Date: | August 10, 2021 |
| Contractor: | | Subcontractor: | |
| Location(s) Inspected: | Km 66 | | |
| Current Stage of Operation: | on-going | | |
| Program Modifications Approved: | | | |

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

| Operating Condition | Aspect Inspected | | | | |
|---|------------------|--|--|--|--|
| | Km 66 | | | | |
| Location as Permitted | A | | | | |
| Time as Permitted | A | | | | |
| Equipment as Approved (Type & Size) | A | | | | |
| Methods & Techniques | A | | | | |
| Erosion (Control or Prevention) | A | | | | |
| Wildlife and Fisheries Habitat (Protection) | A | | | | |
| Brush Disposal | A | | | | |
| Restoration of Lands | A | | | | |
| Permits | A | | | | |
| Matters not Inconsistent | A | | | | |
| Sections 8 to 12 / 14 to 16 M.V.L.U.R. | A | | | | |
| Chemicals | A | | | | |

Explanatory Remarks -

Km 66:

During the inspection at Km 66 on August 10, 2021 there were no concerns observed by the inspector.

There is no work being conducted at the site at this time of the inspection.

The site looks clean and in good order



Representative Signature



Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:
Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

