



Telephone: 867-777-8905  
Fax: 867-777-2090

May 27, 2019

GNWT Industry, Tourism and Investment  
P.O. Box 2589  
Inuvik, NT  
X0E 0T0

**Attention: John Cournoyea**

<b>File Number</b>	<b>G17X001</b>
<b>Type of Operation</b>	<b>MISC.</b>
<b>Location</b>	Weather shelter

Dear John Cournoyea,

An inspection of the above noted operation was conducted on May 22, 2019 by Resource Management Officer I Bradley Voudrach and Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-777-8905.

Sincerely,

**ORIGINAL SIGNED**

Bradley Voudrach  
Resource Management Officer I  
Department of Lands  
Beaufort Delta Region

CC:

Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region  
AlecSandra Macdonald, Regulatory Specialist, Gwich'in Land and Water Board



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	GNWT Industry, Tourism and Investment	<b>Permit Expiry Date:</b>	March 28, 2022
<b>Land Use Permit No.</b>	G17X001	<b>Previous Inspection:</b>	New
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	May 22, 2019
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	Weather shelter		
<b>Current Stage of Operation:</b>	Construction complete. Land Use Permit currently active until March 2022.		
<b>Program Modifications Approved:</b>			

**Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected**

Operating Condition	Aspect Inspected				
	Weather Shelter				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Wildlife and Fisheries Habitat (Protection)	A				
Historical / Archaeological Sites	A				
Ecological Resources	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

Explanatory Remarks -

**Weather Shelter :**

During this initial inspection it was observed that the structure appeared to be stable. It was constructed as per the design on a mound of crushed rock with a freeboard of approximately 3 metres on each side. There is a drainage ditch to the east (approximately 2-3 metres) that appears to be very effective at draining water.

\_\_\_\_\_  
Representative Signature

\_\_\_\_\_  
Inspector's Signature

Date:	May 22, 2019	Permit #:	G17X001	Page No:	1
-------	--------------	-----------	---------	----------	---



## ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

**Figure 1**

A picture of the structure from a westerly direction looking in a easterly direction, with the Dempster Highway #8 bridge in the background.



**Figure 2**

A picture of the structure from the south-end, looking north.





# ENVIRONMENTAL INSPECTION REPORT

Date:	May 22, 2019	Permit #:	G17X001	Page No:	3
-------	--------------	-----------	---------	----------	---