



Telephone: 867-777-8907
Fax: 867-777-2090

April 13, 2022

NWT Energy Corporation (03) Ltd.
4 Capital Drive
Hay River, NT XOE 1G2

Attention: Bruno Pereira

File Number	G18X005
Type of Operation	MISC.
Location	Wind tower access and Km 251 quarry

Dear Bruno Pereira,

An inspection of the above noted operation was conducted on April 12, 2022 by Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC:
Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region

GLWB



ENVIRONMENTAL INSPECTION REPORT

FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF March 31, 2022

LUP Terms and Conditions and the Quarry Permit Terms and conditions are to be followed.

Permittee:	NWT Energy Corporation (03) Ltd.	Permit Expiry Date:	November 26, 2025
Land Use Permit No.	G18X005	Previous Inspection:	March 31, 2022
Quarrying Permit No.	2021QP0032 - for 300,000cm	Inspection Date:	April 12, 2022
Contractor:		Subcontractor:	
Location(s) Inspected:	Wind tower access and Km 251 quarry		
Current Stage of Operation:	On-going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	KM 251	Wind tower access			
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wastes	A				
Ecological Resources	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Location as Permitted		A			
Time as Permitted		A			
Equipment as Approved (Type & Size)		A			
Methods & Techniques		A			
Facilities		A			
Wastes		A			
Ecological Resources		A			
Fuel Storage		A			
Brush Disposal		A			
Restoration of Lands		A			
Permits		A			
Matters not Inconsistent		A			
Sections 8 to 12 / 14 to 16 M.V.L.U.R.		A			
Erosion (Control or Prevention)		A			
Chemicals		A			
Wildlife and Fisheries Habitat (Protection)		A			



ENVIRONMENTAL INSPECTION REPORT

Explanatory Remarks -

KM 251:

During the inspection on April 12, 2022 at Km 251 quarry there was one concern that was observed by the inspector.

There is a lot of material stock piled in different locations on the pit floor at the site and could be hazardous for operators maneuvering equipment around in the area.

At the quarry site they have a monitor, Barry Cook who is monitoring for spills and will be cleaning up any spills if they occur at the site.

Wind tower access:

During the inspection at wind tower access road, there was one concern observed by the inspector. There is some plastic wrapping and paper tubing in a couple of places that needs to be removed before the wind takes it away.

I met up with Rob Adams, President of ONEC, Northern Operations and Scott Dimitroff, Senior Project Technologist for Tetra Tech during my inspection and Scott was keeping track of the work that is being conducted at the site. I had a conversation with both Rob and Scott to go over what the Inspector will look for during an inspection at the work site. Scott indicated he will have the garbage cleaned up before the end of the day.

It would be beneficial for the site supervisors to have a copy of the project description and terms and conditions of their land use permit and follow them to ensure they keep in compliance.

Department of Lands are receiving the weekly progress reports which give us an idea of what is being conducted before we get out to the site for our inspections.

Representative Signature

Inspector's Signature

Date:	April 12, 2022	Permit #:	G18X005	Page No:	2
-------	----------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1
Km 251(1)



Figure 2
Km 251(2)





ENVIRONMENTAL INSPECTION REPORT

Figure 3
KM 251(3)



Figure 4
Km 251(4)





ENVIRONMENTAL INSPECTION REPORT

Figure 5
Wind tower Access(1)



Figure 6
Wind tower Access(2)





ENVIRONMENTAL INSPECTION REPORT

Figure 7
Wind tower Access(3)



Figure 8
Wind tower Access(4)

