



Telephone: 867-777-8907
Fax: 867-777-2090

March 9, 2022

NWT Energy Corporation (03) Ltd.
4 Capital Drive
Hay River, NT XOE 1G2

Attention: Bruno Pereira

File Number G18X005
Type of Operation MISC.
Location Wind tower access

Dear Bruno Pereira,

An inspection of the above noted operation was conducted on March 08, 2022 by Resource Management Officer II Herbert Allen and Manager, Resource Management Donald Arey.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC:

Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region

GLWB

Bag Service 1, Inuvik, NT XOE 0T0



ENVIRONMENTAL INSPECTION REPORT

Permittee:	NWT Energy Corporation (03) Ltd.	Permit Expiry Date:	November 26, 2025
Land Use Permit No.	G18X005	Previous Inspection:	March 02, 2022
Quarrying Permit No.	2021QP0032 - for 300,000cm	Inspection Date:	March 08, 2022
Contractor:		Subcontractor:	
Location(s) Inspected:	Wind tower access		
Current Stage of Operation:	starting of project		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	KM 251			
Location as Permitted	A			
Time as Permitted	A			
Equipment as Approved (Type & Size)	A			
Methods & Techniques	A			
Facilities	A			
Erosion (Control or Prevention)	A			
Chemicals	A			
Wildlife and Fisheries Habitat (Protection)	A			
Wastes	A			
Historical / Archaeological Sites	A			
Ecological Resources	A			
Brush Disposal	A			
Restoration of Lands	A			
Permits	A			
Matters not Inconsistent	A			
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A			

Explanatory Remarks - KM 251:


During the inspection on March 8, 2022 along the access trail to the wind tower site there were no concerns observed by the inspectors.

At the time of the inspection there was a cat and a skid steer mulching the trail to the site, they were not quite there but getting close. There was also a surveyor working along the access staking the trail and a person on snowmobile collecting all the trees that were cut down along the path and piling them at the entrance by the highway.

There is no material being hauled to the site at this time.



Representative Signature



Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

