



Telephone: 867-678-8090 ext. 24653
Fax: 867-777-2090

November 3, 2022

NWT Energy Corporation (03) Ltd.
4 Capital Drive
Hay River, NT XOE 1G2

Attention: Bruno Pereira

File Number: G18X005
Type of Operation: MISC.
Location: Wind tower pad and access road and Km 251 quarry

Dear Bruno Pereira,

An inspection of the above noted operation was conducted on November 01, 2022 by Manager, Resource Management Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

Department of Lands require the quantity of material quarried and the quantity of material removed from the site during the period of October 1st to September 30th

If you have any questions, please contact me at 867-678-8090 ext. 24653.

Sincerely,

Herbert Allen
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC:
Donald Arey, Regional Superintendent, Department of Lands, Beaufort Delta Region
GLWB

Bag Service 1, Inuvik, NT XOE OT0



ENVIRONMENTAL INSPECTION REPORT

Permittee:	NWT Energy Corporation (03) Ltd.	Permit Expiry Date:	November 26, 2025
Land Use Permit No.	G18X005	Previous Inspection:	October 20, 2022
Quarrying Permit No.	2021QP0032 - for 300,000cm	Inspection Date:	November 01, 2022
Contractor:		Subcontractor:	
Location(s) Inspected:	Wind tower pad and access road and Km 251 quarry		
Current Stage of Operation:	On-going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Wind Tower access and pad	Km 251 quarry			
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Fuel Storage	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Sections 12 to 19 T.L.U.R.	A				
Location as Permitted		A			
Equipment as Approved (Type & Size)		A			
Methods & Techniques		A			
Facilities		A			
Erosion (Control or Prevention)		A			
Fuel Storage		A			
Brush Disposal		A			
Restoration of Lands		A			
Matters not Inconsistent		U			
Sections 12 to 19 T.L.U.R.		A			



ENVIRONMENTAL INSPECTION REPORT

Explanatory Remarks –

Wind Tower access and pad:

During the inspection on November 1, 2022 at the Wind tower pad and access road, there were no concerns observed by the inspector.

There were two work crews at the site, a crew from Surespan and a crew from LaPrairie Crane working on the foundation at the site.

The work site is clean and looked in good order.

At the time of the inspection there was no one working on the access road but the worker at the tower pad site indicated they were working on the road earlier that day.

Km 251 quarry:

During the inspection at the km 251 quarry site there was one concern observed by the inspector.

Department of Lands require the quantity of material quarried and the quantity of material removed from the site during the period of October 1st to September 30th

Quarry Permit Conditions:

13. Prior to October 1st annually, the Permittee shall submit a report to the Land Use Inspector indicating the quantity of material quarried and the quantity of material removed from the site during the period of October 1st to September 30th. Failure to submit the annual report within indicated time may result in cancellation of this permit as per section 9(6) of the regulations.

The work area for the material extraction looked in good order and there were no concerns by the inspector.

Representative Signature

Inspector's Signature

Date:	November 01, 2022	Permit #:	G18X005	Page No:	2
-------	-------------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3




Figure 4





ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6

