



Telephone: 867-777-8907

Fax: 867-777-2090

July 25, 2022

NWT Energy Corporation (03) Ltd.
4 Capital Drive
Hay River, NT XOE 1G2

Attention: **Bruno Pereira**

File Number G18X005
Type of Operation MISC.
Location High point tower pad and access road

Dear Bruno Pereira,

An inspection of the above noted operation was conducted on July 21, 2022 by Manager of Resource Management Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Manager of Resource Management
Department of Lands
Beaufort Delta Region

CC:

Donald Arey, Regional Superintendent, Department of Lands, Beaufort Delta Region

GLWB

ENVIRONMENTAL INSPECTION REPORT

Permittee:	NWT Energy Corporation (03) Ltd.	Permit Expiry Date:	November 26, 2025
Land Use Permit No.	G18X005	Previous Inspection:	June 30, 2022
Quarrying Permit No.	2021QP0032 - for 300,000cm	Inspection Date:	July 21, 2022
Contractor:		Subcontractor:	
Location(s) Inspected:	High point tower pad and access road		
Current Stage of Operation:	On-going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Wind Tower access and pad				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Fuel Storage	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Sections 12 to 19 T.L.U.R.	A				

Explanatory Remarks - Wind Tower access and pad:

During the inspection on July 21, 2022 at the high point tower pad and access road there is a couple of concerns that was observed by the inspector.

There are a couple of soft spots along the access road that is getting to be a concern and may cause vehicles and heavy equipment to get stuck. The two areas are closer to the top of the access road that should be filled in to prevent a sink hole.

There was a crew from Arctic Foundations out of Winnipeg installing the condensers for the foundation. The crew was on their last day of work at the site. there was just a few little pieces of plastic trash around the work area and the crew leader Mike Watt indicated they will clean it up before they leave.

The rest of the site looked in good order.



Representative Signature



Inspector's Signature

Date:	July 21, 2022	Permit #:	G18X005	Page No:	1
-------	---------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:
Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6





ENVIRONMENTAL INSPECTION REPORT

Figure 7



Figure 8

