



Telephone: 867-777-8907  
Fax: 867-777-2090

June 3, 2022

NWT Energy Corporation (03) Ltd.  
4 Capital Drive  
Hay River, NT XOE 1G2

Attention: Bruno Pereira

File Number G18X005  
Type of Operation MISC.  
Location Wind tower access and tower site

Dear Bruno Pereira,

An inspection of the above noted operation was conducted on June 02, 2022 by Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report.

Department of Lands would like a copy of the engineering drawings and plans for the next stages in the project to ensure we are kept up to speed and the inspectors know what to expect on future inspections.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen  
Resource Management Officer II  
Department of Lands  
Beaufort Delta Region

CC:

Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region

GLWB

Bag Service 1, Inuvik, NT XOE OT0



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	NWT Energy Corporation (03) Ltd.	<b>Permit Expiry Date:</b>	November 26, 2025
<b>Land Use Permit No.</b>	G18X005	<b>Previous Inspection:</b>	May 26, 2022
<b>Quarrying Permit No.</b>	2021QP0032 - for 300,000cm	<b>Inspection Date:</b>	June 02, 2022
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	wind tower access and tower site		
<b>Current Stage of Operation:</b>	on-going		
<b>Program Modifications Approved:</b>			

**Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected**

Operating Condition	Aspect Inspected				
	<b>Wind Tower access and pad</b>				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Fuel Storage	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Sections 12 to 19 T.L.U.R.	A				

**Explanatory Remarks -**

**Wind Tower access and pad:**

During the inspection at the wind tower access and wind tower site there were no concerns observed by the inspector.

It appears all the pilings are installed for the wind tower and there is no work activity at the site at the time of the inspection. Rob Adams indicated the next phase of work will be commencing soon at the wind tower site.

The work on widening and building up the road is still in progress and moving forward. There is less ponding water along the road but where there is water in an area the road was a little soft and you can see the moisture on some parts of the road.

Department of Lands is yet to receive a copy of the engineering drawings and plans for the next stages in the project to ensure we are kept up to speed and the inspectors know what to expect on future inspections.



# ENVIRONMENTAL INSPECTION REPORT

--

*NA*

Representative Signature

Inspector's Signature



# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:  
**Figure 1**



**Figure 2**





# ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





# ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6

