



Telephone: 867-777-8907  
Fax: 867-777-2090

July 14, 2021

GNWT Department of Infrastructure  
Bag Service 1  
Inuvik, NT X0E 0T0

**Attention: Mosiul Alam**

**File Number** G19Q005  
**Type of Operation** QUARRY SITE - New  
**Location** Km 147

Dear Mosiul Alam,

An inspection of the above noted operation was conducted on July 13, 2021 by Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen  
Resource Management Officer II  
Department of Lands  
Beaufort Delta Region

CC:  
Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region  
GLWB  
GTC

Bag Service 1, Inuvik, NT X0E 0T0



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	GNWT Department of Infrastructure	<b>Permit Expiry Date:</b>	April 17, 2023
<b>Land Use Permit No.</b>	G19Q005	<b>Previous Inspection:</b>	June 23, 2021
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	July 13, 2021
<b>Contractor:</b>	Allen's Services	<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	Km 147		
<b>Current Stage of Operation:</b>	complete		
<b>Program Modifications Approved:</b>			

**Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected**

Operating Condition	Aspect Inspected				
	<b>Km 147</b>				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Erosion (Control or Prevention)	A				
Wildlife and Fisheries Habitat (Protection)	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				

**Explanatory Remarks -**

Km 147:

During the inspection on July 13, 2021 at Km 147 there were no concerns observed by the inspector.

The camp operation at the site was closed down as the work in that section of the highway was completed and the camp was no longer needed.

All the camp buildings and equipment are removed from the site except for a few small gravel piles which are of no concern. The area where gravel was extracted from the pit was restored to the required conditions of the permit. The site looks clean and in good order.

There will be a final inspection conducted with Department of Lands and GTC Lands and Resources at the site next week.

Representative Signature

Inspector's Signature



# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:  
**Figure 1**



**Figure 2**





# ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





# ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6

