



Telephone: 867-678-8090 ext. 24653

Fax: 867-777-2090

March 21, 2024

Northwind Industries Ltd.  
P.O. Box 1130  
Inuvik, NT X0E0T0

**Attention: Fred Bailey**

<b>File Number</b>	<b>G19Q009</b>
<b>Type of Operation</b>	<b>QUARRY SITE - Existing</b>
<b>Location</b>	<b>Km 251</b>

Dear Fred Bailey,

An inspection of the above noted operation was conducted on March 20, 2024 Resource Management Officer Herbert Allen and Resource Management Officer Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report

If you have any questions, please contact me at 867-678-8090 ext. 24653.

Sincerely,

Herbert Allen  
Resource Management Officer  
Department of Environment and  
Climate Change Land and Water  
Beaufort Delta Region

Donald Arey, Acting Regional Superintendent, Department of Environment and Climate Change Land and Water, Beaufort Delta Region  
GLWB

### ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	Northwind Industries Ltd.	<b>Permit Expiry Date:</b>	December 02, 2024
<b>Land Use Permit No.</b>	G19Q009	<b>Previous Inspection:</b>	March 04, 2024
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	March 20, 2024
<b>Contractor:</b>	Northwind	<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	Km 251		
<b>Current Stage of Operation:</b>			
<b>Program Modifications Approved:</b>			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	<b>Km 251</b>				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Historical / Archaeological Sites	A				
Ecological Resources	A				
Fuel Storage	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

**Explanatory Remarks - Km 251:**

During the inspection at Km 251 on Mzrch 20, 2024 there were no concerns abserved by the inspectors.

The contractors at the site were drilling for their next blast and material were getting sorted for trucking.

The rest of the site looked in good order.

  
 Representative Signature

  
 Inspector's Signature



# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:  
**Figure 1**



**Figure 2**





# ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

