



Telephone: 867-777-8907

Fax: 867-777-2090

August 25, 2022

Department of Infrastructure  
Bag service # 1  
106 Veteran Way  
Inuvik, NT X0E0T0

**Attention: Mosiul Alam**

**File Number** G21E001  
**Type of Operation** HWY MAINTENANCE & OPERATIONS  
**Location** Km 251

Dear Mosiul Alam,

An inspection of the above noted operation was conducted on August 23, 2022 by Manager of Resource Management Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen  
Manager of Resource Management  
Department of Lands  
Beaufort Delta Region

CC:  
Donald Arey, Regional Superintendent, Department of Lands, Beaufort Delta Region

GLWB

Bag Service 1, Inuvik, NT X0E 0T0



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	Department of Infrastructure	<b>Permit Expiry Date:</b>	June 27, 2026
<b>Land Use Permit No.</b>	G21E001	<b>Previous Inspection:</b>	July 21, 2022
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	August 23, 2022
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	Km 251		
<b>Current Stage of Operation:</b>	On-going		
<b>Program Modifications Approved:</b>			

**Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected**

Operating Condition	Aspect Inspected	Operation			
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Historical / Archaeological Sites	A				
Ecological Resources	A				
Fuel Storage	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Location as Permitted	A				

**Explanatory Remarks - Operation :**

During the inspection on August 23, 2022 at Km 251 quarry site there were no concerns observed by the inspector.

There was very little activity at the site, there was 1 excavator loading up gravel trucks at the northwest section of the pit and 1 person working on equipment at the top of the northwest section access and there was no crushing occurring at the time of the inspection.

There is one large stock pile of material in the center of the pit and the crusher set up near the back of the pit.

There is a lot more open space on the pit floor and the site is clean and looks in good order.

Please submit a pre and post data for the material used for the highway maintenance to date.

Representative Signature

Inspector's Signature

Date:	August 23, 2022	Permit #:	G21E001	Page No:	1
-------	-----------------	-----------	---------	----------	---



# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

**Figure 1**



**Figure 2**





# ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





# ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6

