



Telephone: 867-777-8907

Fax: 867-777-2090

July 4, 2022

Department of Infrastructure
Bag service # 1
106 Veteran Way
Inuvik, NT X0E0T0

Attention: **Mosiul Alam**

File Number G21E001
Type of Operation HWY MAINTENANCE & OPERATIONS
Location Km 251

Dear Mosiul Alam,

An inspection of the above noted operation was conducted on June 30, 2022 by Acting Manager of Resource Management, Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Acting Manager of Resource Management
Department of Lands
Beaufort Delta Region

CC: Donald Arey, Acting Regional Superintendent, Department of Lands, Beaufort Delta Region

GLWB



ENVIRONMENTAL INSPECTION REPORT

FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF June 13, 2022

Stock piles are to be removed from site as this is a multi user source and safe maneuverability may be a risk.

Permittee:	Department of Infrastructure	Permit Expiry Date:	June 27, 2026
Land Use Permit No.	G21E001	Previous Inspection:	June 13, 2022
Quarrying Permit No.		Inspection Date:	June 30, 2022
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 251		
Current Stage of Operation:	On-going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Operation				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Historical / Archaeological Sites	A				
Ecological Resources	A				
Fuel Storage	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Location as Permitted	A				

Explanatory Remarks - Operation :

During the inspection at Km 251 on June 30, 2022 there were no concerns observed by the inspector.

There is an excavator working at the mid section of the north portion of the pit wall to keep the activity rolling as the last blast area needs to be cleared and benched for a safe work area. Please ensure that there is an access road to the back sections of the pit at all times.

It appears at this time there is only hauling of material for the wind tower project out of Km 251.

Please ensure that the pre and post data are submitted to Department of Lands as indicated below.

As per conditions of your QP 2022QP0001;

1. "The Permittee will identify the work area to the satisfaction of the Land Use Inspector prior to the removal of any material and any change in location will require prior approval of the



ENVIRONMENTAL INSPECTION REPORT

Land Use Inspector.

2. All surveyed data submitted (including pre and post blasts if applicable) shall be in a electronic format with waypoints, shape files and excel spreadsheets compatible with ArcGIS 9.3 or as approved by a Land Use Inspector.
3. Pre and post surveys, must be conducted by a certified Canada Land Surveyor or certified engineering technician or as approved by the land use inspector.
4. Pre-surveys must be submitted to the land use inspector, 10 days prior to the commencement of operations, for approval
5. Post-surveys must be submitted to the land use inspector within 60 days of completion of the operation.
6. Pit/Quarry operations in all territorial pits, including multi user pits, must be coordinated by the Land Use Inspector and be conducted as per the quarry permit application and/or Pit Management/Development Plan.
7. The Permittee will not work any area worked by any other Permittee except as coordinated by the Land Use Inspector.

Please ensure that the PDP is followed at all times.

Representative Signature

Inspector's Signature

Date:	June 30, 2022	Permit #:	G21E001	Page No:	2
-------	---------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:
Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

