



Telephone: 867 777-8900
Fax: 867-777-2090

June 14, 2022

Department of Infrastructure
Bag service # 1
106 Veteran Way
Inuvik, NT X0E0T0

Attention: Mosiul Alam

File Number G21E001
Type of Operation HWY MAINTENANCE & OPERATIONS
Location Km 251


To: Mosiul Alam,

An inspection of the above noted operation was conducted on June 13, 2022 by Manager, Resource Management Donald Arey and Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.


If you have any questions, please contact me at 867 777-8900.

Regards,


Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC: GLWB

Bag Service #1, Inuvik, NT X0E 0T0





ENVIRONMENTAL INSPECTION REPORT

Permittee:	Department of Infrastructure	Permit Expiry Date:	June 27, 2026
Land Use Permit No.	G21E001	Previous Inspection:	June 13, 2022
Quarrying Permit No.		Inspection Date:	June 13, 2022
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 251		
Current Stage of Operation:	2021QP0032 - High wind Project		
Program Modifications Approved:	Nil		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	Operation			
Time as Permitted	A			
Equipment as Approved (Type & Size)	A			
Methods & Techniques	A			
Facilities	A			
Erosion (Control or Prevention)	A			
Chemicals	U			
Wildlife and Fisheries Habitat (Protection)	A			
Wastes	A			
Historical / Archaeological Sites	A			
Ecological Resources	A			
Fuel Storage	A			
Brush Disposal	A			
Restoration of Lands	A			
Permits	A			
Matters not Inconsistent	A			
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A			
Location as Permitted	A			

Explanatory Remarks -

Operation :

During this inspection conducted under Quarry Permit 2021QP0032, it was observed that numerous equipment spills were on the pit floor, an employee working at site was informed of the spills and was currently cleaning them up.

Contractor had informed that there was a concern in regards to material being stock piled at the site for the GNWT INF O&M road widening, inspector looked into the matter and further did an inspection report for this. Further that 2021QP0032 is for the High Wind Project.

It was learned as well that a blast may have not blasted, however upon further enquiries it



ENVIRONMENTAL INSPECTION REPORT

was learned that this blast was verified.

Drilling as well was in progress for the next blast at the location.

Please ensure that the PDP and quarry permits are followed at all times.

MATTERS FOR FOLLOW UP

Ensure PDP and Quarry Permits are followed.

N/A
Representative Signature

[Signature]
Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:
Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





ENVIRONMENTAL INSPECTION REPORT

Figure 5




Figure 6

