



Telephone: 867-678-8090 ext. 24653
Fax: 867-777-2090

April 4, 2025

Department of Infrastructure
106 Veterans Way
Bag Service #1
Inuvik, NT X0E0T0

Attention: Yasir Latif

File Number	G23H002
Type of Operation	CAMPS
Location	Km 14.2 James Creek

Dear Yasir Latif ,

An inspection of the above noted operation was conducted on April 03, 2025 by Manager, Resource Management Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-678-8090 ext. 24653.

Sincerely,

Herbert Allen

Herbert Allen
Resource Management Officer
Department of Environment and Climate
Change Land and Water
Beaufort Delta Region

CC:
Donald Arey, Regional Superintendent, ECC Land and Water, Beaufort Delta Region
GLWB



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Department of Infrastructure	Permit Expiry Date:	September 11, 2028
Land Use Permit No.	G23H002	Previous Inspection:	February 25, 2025
Quarrying Permit No.		Inspection Date:	April 03, 2025
Contractor:	LJ's	Subcontractor:	
Location(s) Inspected:	Km 14.2 James Creek		
Current Stage of Operation:			
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	Camp			
Location as Permitted	A			
Time as Permitted	A			
Equipment as Approved (Type & Size)	A			
Facilities	A			
Chemicals	U			
Wastes	A			
Fuel Storage	A			

Explanatory Remarks - Camp:

During the inspection at the James Creek camp on April 3, 2025 there was one concern observed by the inspector.

There is a leak under the Volvo loader that is parked at the west side of the site near the red trailer. A drip tray should be placed under the loader and repaired or removed from the site.

The rest of the site looks clean and in good order.

N/A

Representative Signature

Herbert Allen

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6

