



Telephone: 867-678-8090 ext. 24653
Fax: 867-777-2090

February 29, 2024

Department of Infrastructure
106 Veterans Way
Bag Service #1
Inuvik, NT X0E0T0

Attention: Shah Alam

File Number G23H002
Type of Operation CAMPS - < 50 Man Camp
Location James Creek Km 14.2

Dear Shah Alam,

An inspection of the above noted operation was conducted on February 28, 2024 by Manager, Resource Management Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-678-8090 ext. 24653.

Sincerely,

Herbert Allen
Resource Management Officer
Department of Environment and Climate
Change Land and Water
Beaufort Delta Region

CC:

Donald Arey, Regional Superintendent, Department of Environment and Climate Change Land and Water, Beaufort Delta Region
GLWB

ENVIRONMENTAL INSPECTION REPORT

Permittee:	Department of Infrastructure	Permit Expiry Date:	September 11, 2028
Land Use Permit No.	G23H002	Previous Inspection:	February 13, 2024
Quarrying Permit No.		Inspection Date:	February 28, 2024
Contractor:	LJ's	Subcontractor:	
Location(s) Inspected:	James Creek Km 14.2		
Current Stage of Operation:			
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Camp				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	U				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Historical / Archaeological Sites	A				
Fuel Storage	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

Explanatory Remarks - Camp:

During the inspection on February 28, 2024 there was 1 concern that was observed by the inspector.

The hydraulic fluid leak from the snow cat was not cleaned which was indicated in the last inspection report. The part that is leaking should be repaired and hydraulic fluid cleaned up.

The hydraulic fluid spill that was in front of the garage indicated in the last inspection report was cleaned up.

The rest of the site looks in good order.



Representative Signature



Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:
Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

