



Dehcho Region  
Box 150  
Fort Simpson, NT X0E 0N0

Telephone: 867 695-2626  
Fax: 867 695-2615

May 2, 2014

Enbridge Pipelines (NW) Inc  
PO Box 280

Norman Wells, NT X0E 0V0

**Attn: Ann Marie Tout**

**RE: Land Use Permit MV2013P0011  
PIPELINES (existing)  
KP 385 Camp Integrity Dig site KP 387**

Dear Ann Marie Tout,

An inspection of the above noted operation was conducted on March 04, 2014 by Manager Resource Management Laurie Nadia.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867 695-2626.

Sincerely,

A handwritten signature in blue ink that reads "L. Nadia".

Laurie Nadia  
Manager Resource Management  
«INSP\_DEPARTMENT»  
Dehcho Region

Cc: Charlene Coe, Land Use Advisor, Yellowknife  
MVLWB



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	Enbridge Pipelines (NW) Inc	<b>Permit Expiry Date:</b>	July 17, 2018
<b>Land Use Permit No.</b>	MV2013P0011	<b>Previous Inspection:</b>	New
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	March 04, 2014
<b>Contractor:</b>	Ledcore	<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	KP 385 Camp Integrity Dig site KP 387		
<b>Current Stage of Operation:</b>	Active		
<b>Program Modifications Approved:</b>	None		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	KP 385/Smith Creek Camp	Integrity Dig Site KP 387			
Brush Disposal	A				
Chemicals	A	A			
Equipment as Approved (Type & Size)	A	A			
Erosion (Control or Prevention)		A			
Facilities	A	A			
Fuel Storage	A				
Location as Permitted	A	A			
Matters not Inconsistent	A	A			
Methods & Techniques	A	A			
Permits	A	A			
Restoration of Lands		A			
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A	A			
Time as Permitted	A	A			
Wastes	A				

**Explanatory Remarks -**

Integrity Dig Site KP 387:

This dig site was clean and tidy. The Inspector had no concerns at the time of this inspection

KP 385/Smith Creek Camp:

This camp site was kept very clean and well laid out. The Inspector had no concerns at the time of this inspection.

## ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

### Figure 1

Smith Creek Camp fuel properly stored with secondary containment and double walled top feeding tanks

---



## ENVIRONMENTAL INSPECTION REPORT

**Figure 2**

**Smith Creek Camp Sewage treatment facility with all solids being transported to the Hay River Sewage Facility**



**Figure 3**

**Smith Creek Camp water supply**



## ENVIRONMENTAL INSPECTION REPORT

**Figure 4**

**Smith Creek Camp forced air incinerator. Site was very clean and well kept.**



**Figure 5**

**Integrity dig site. Very little disturbance during this phase of the exposure.**

