



South Slave Region  
41 Capital Drive #203  
Hay River, NT X0E 1G2

Telephone: 867 874-6994  
Fax: 867 874-2460

October 5, 2015

ProCore Drilling Ltd.  
28067B Mackenzie Highway  
Hay River, NT X0E 0R4

**Attn: Darrel Dean**

**RE: Land Use Permit MV2013Q0017  
QUARRY SITE - New  
Sites A & C, Km 34.1, NWT Highway No. 5**

Dear Mr. Dean,

An inspection of the above noted operation was conducted on August 27, 2015 by Resource Management Officers Jayda Robillard and Resource Management Officer Norm McCowan.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

Please note Condition 11 of your quarry permit requires you to submit a monthly quarry report to this office prior to the 10th day of each month. **Failure to submit a monthly report may result in cancellation of your quarry permit.**

If you have any questions, please contact me at 867 874-6994.

Sincerely,

**ORIGINAL SIGNED**

Jayda Robillard  
Resource Management Officer II  
Department of Lands  
South Slave Region

Cc: MVLWB



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	ProCore Drilling Ltd.	<b>Permit Expiry Date:</b>	May 21, 2019
<b>Land Use Permit No.</b>	MV2013Q0017	<b>Previous Inspection:</b>	May 07, 2015
<b>Quarrying Permit No.</b>	2014QP0054	<b>Inspection Date:</b>	August 27, 2015
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	Sites A & C, Km 34.1, NWT Highway No. 5		
<b>Current Stage of Operation:</b>	A significant amount of granular material has been quarried from Sites A and C this season under the authority of quarry permit #2014QP0054. A loader is currently parked at the Site C location.		
<b>Program Modifications Approved:</b>			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Site A	Site C			
Brush Disposal	N/A	N/A			
Chemicals	A	A			
Ecological Resources		A			
Equipment as Approved (Type & Size)	A	A			
Erosion (Control or Prevention)	A	A			
Facilities	A	U (11)			
Fuel Storage	U (32, 35, 36)	U (32, 35, 36)			
Historical / Archaeological Sites	N/A	N/A			
Location as Permitted	A	A			
Methods & Techniques		A			
Permits	A	A			
Restoration of Lands	N/A	N/A			
Time as Permitted	A	A			
Wastes	A	U(25)			
Wildlife and Fisheries Habitat (Protection)	A	A			

**Explanatory Remarks -**

**Site A:**

A large amount of material has been quarried from the two stockpiles at Site A. **Please ensure that this material is reported in your monthly quarry report to this office as per Condition 11 of your quarry permit.**

**Condition 36:** There are several fuel stains near the stockpile at the entrance to Site A. The contaminated soil must be cleaned up and taken to an authorized disposal area. See comments for Site C regarding repairing leaking equipment and using drip-trays.

**Site C:**

A large amount of granular material has been removed from the stockpiles at Site C this season. **Please ensure that this material is reported in your monthly quarry report to this office as per Condition 11 of your quarry permit.**

**Condition 32 and 36:** There are several fuel stains near the large stockpile which must be cleaned up and taken to an authorized disposal area. Repairs must be made to your loader to prevent further spills from happening.

**Condition 35** of your land use permit requires "All equipment that may be parked for 2 hours or more, should have a haz-mat/drip tray under it or be sufficiently diapered. (Leaky equipment should be repaired immediately)." There was no haz-mat/drip tray under the loader at the time of inspection.

**Condition 25 and 11:** As identified in the previous inspection reports, the old dryer still has not been removed from territorial lands and taken to an authorized disposal area.



# ENVIRONMENTAL INSPECTION REPORT

\_\_\_\_\_  
Representative Signature

\_\_\_\_\_  
ORIGINAL SIGNED  
Inspector's Signature

Date:	August 27, 2015	Permit #:	MV2013Q0017	Page No:	2
-------	-----------------	-----------	-------------	----------	---

## ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

**Figure 1**

Site A stockpile - a large amount of material has been removed this season.



**Figure 2**

Stockpile at the entrance to Site A - material has been removed this season.



**Figure 3**

Fuel stains near the stockpile at the entrance to Site A.



**Figure 4**

More fuel stains near the stockpile at the entrance to Site A.



**Figure 5**

Site C - material has been removed from this stockpile this season.



**Figure 6**

Site C - fuel stains near the stockpile.



## ENVIRONMENTAL INSPECTION REPORT

**Figure 7**  
**Site C - loader parked at large stockpile.**



**Figure 8**  
**Site C - fuel stains on the ground near the large stockpile.**



**Figure 9**  
**Site C - more fuel stains near the large stockpile.**



**Figure 10**  
**Site C - old dryer remains on site.**

