



Telephone: 867 874-6994

Fax: 867 874-2460

October 23, 2018

ProCore Drilling Ltd.  
28067B Mackenzie Highway  
email: ddean@northwestel.net  
Hay River, NT X0E 0R4

**Attention: Darrel Dean**

<b>File Number</b>	<b>MV2013Q0017</b>
<b>Type of Operation</b>	<b>QUARRY SITE - New</b>
<b>Location</b>	<b>Km 34.1, Site A &amp; C, NWT Highway No. 5</b>

Dear Mr. Dean,

An inspection of the above noted operation was conducted on September 28, 2018 by Resource Management Officers Jayda Robillard and Norm McCowan.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated. Your land use permit expires on May 21, 2019. If you wish to apply for a two year extension, please contact the Mackenzie Valley Land and Water Board prior to the expiry date.

If you have any questions, please contact me at 867 874-6994.

Sincerely,

Jayda Robillard  
Resource Management Officer II  
Department of Lands  
South Slave Region

CC: Mackenzie Valley Land and Water Board  
Charlene Coe, Land Use Advisor North Slave – GNWT Dept of Lands  
Derise Rehm-Lepine, Regional Superintendent South Slave – GNWT Dept of Lands



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	ProCore Drilling Ltd.	<b>Permit Expiry Date:</b>	May 21, 2019
<b>Land Use Permit No.</b>	MV2013Q0017	<b>Previous Inspection:</b>	June 20, 2018
<b>Quarrying Permit No.</b>	2017QP0025	<b>Inspection Date:</b>	September 28, 2018
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	Km 34.1, Site A & C, NWT Highway No. 5		
<b>Current Stage of Operation:</b>	Site C quarry has been active this season.		
<b>Program Modifications Approved:</b>			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Site A	Site C			
Location as Permitted	A	A			
Time as Permitted	A	A			
Equipment as Approved (Type & Size)	A	A			
Methods & Techniques	A	A			
Facilities	A	A			
Erosion (Control or Prevention)	A	A			
Chemicals	A	A			
Wildlife and Fisheries Habitat (Protection)	A	A			
Wastes	A	A			
Historical / Archaeological Sites	A	A			
Fuel Storage	A	U			
Brush Disposal	A	A			
Restoration of Lands	N/A	A			
Permits	A	A			
Matters not Inconsistent	A	A			

Explanatory Remarks -

**Site C:**

The Permittee has been quarrying in Site C this season under the authority of quarry permit # 2017QP0025. Quarrying activity has taken place at the west end of the pit and from the large stockpile in the central part of the pit. The slopes on the large stockpile have been reduced which will prevent swallows from nesting in the stockpile in the spring.

An excavator is located at the west end of the quarry and has been digging in this area. The excavator has been parked without a drip tray which is in contravention of land use permit **Condition 35** which states "All equipment that may be parked for two hours or more, should have a haz-mat/drip tray under it or be sufficiently diapered. Leaky equipment must be repaired immediately." Please ensure that drip trays are being used under parked equipment at the quarry site.





### ENVIRONMENTAL INSPECTION REPORT

Contouring work will be required at west end of the quarry once the Permittee has depleted this area.

Site A:

There has been no activity in Site A this season.

\_\_\_\_\_  
Representative Signature

  
\_\_\_\_\_  
Inspector's Signature



# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

**Figure 1**

**Site C: Excavator parked at the west end of pit.**



**Figure 2**

**Site C: No drip tray under the Excavator.**



**Figure 3**

**Site C: Permittee has been quarrying at the west end of the pit.**



**Figure 4**

**Site C: A large amount of granular material has been removed from Site C. Slopes have been reduced at the large stockpile.**



**Figure 5**

**Site A: No activity this season.**

