



Telephone: 867-587-7205
Fax: 867-587-2928

July 16, 2019

Husky Oil Operations Limited
707 - 8th Avenue, S.W.
Box 6525 Station D
Calgary, AB T2P 3G7

Attention: Ken Hansen

File Number	S04A-006
Type of Operation	OIL AND GAS DRILLING - WELLSITE
Location	Wellsite L-71

Dear Ken Hansen,

An inspection of the above-noted operation was conducted on July 10, 2019, by Resource Management Officer II Jonathan Gillingham, Resource Management Officer I Bonnie Deschene, and Manager of Resource Management Trevor Bremner.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the noted conditions and the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-587-7205.

Sincerely,

Jonathan Gillingham
Resource Management Officer II
Department of Lands – Sahtu Region

CC: Sahtu Land and Water Board
Trevor Bremner – Manager of Resource Management – Sahtu Region



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Husky Oil Operations Limited	Permit Expiry Date:	September 11, 2009
Land Use Permit No.	S04A-006	Previous Inspection:	July 05, 2016
Quarrying Permit No.	N/A	Inspection Date:	July 10, 2019
Contractor:	N/A	Subcontractor:	N/A
Location(s) Inspected:	Wellsite L-71		
Current Stage of Operation:	Remediation		
Program Modifications Approved:	None		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	L-71				
Time as Permitted	A				
Equipment as Approved (Type & Size)	N/A				
Methods & Techniques	A				
Facilities	N/A				
Location as Permitted	A				
Erosion (Control or Prevention)	A				
Chemicals	N/A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	N/A				
Fuel Storage	N/A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Historical / Archaeological Sites	N/A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

L-71:

As seen in Figure 1, The wellsite has vegetated well. There are a few areas with sparse vegetation (well center and remediated soil). Inspectors were glad to see the water was not pooling at the well center and all equipment as requested in the last inspection report was removed. Figure 2 shows a portion of the remediated soil. Areas within this zone are sparsely vegetated. Figure 3 also displays sparse vegetation growth.

Inspectors wish to retain this permit and continue monitoring the vegetation growth in this area. Once Inspectors are comfortable with this success of the remediation, a discussion of file closure will occur.

Inspectors would like to receive a copy of the seed mixtures used for the phytoremediation and reseeded of this site as soon as possible.



ENVIRONMENTAL INSPECTION REPORT

Representative Signature

Jonathan Dillingham

Inspector's Signature

Date:	July 10, 2019	Permit #:	S04A-006	Page No:	2
-------	---------------	-----------	----------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Aerial view of wellsite L-71.






ENVIRONMENTAL INSPECTION REPORT

Figure 2

WNW corner of the phytoremediation spill area.





ENVIRONMENTAL INSPECTION REPORT

Figure 3
Westside of the Phytoremediated spill area.

