



Telephone: 1-867-587-7205
Fax: 1-867-587-2928

September 30, 2020

HRN Contracting Limited
P.O. Box 329
Norman Wells, NT X0E 0V0

Attention: David Hodgson

File Number	S13Q-004
Type of Operation	QUARRY SITE - New
Location	Quarry

Dear David Hodgson,

An inspection of the above-noted operation was conducted on September 1, 2020, by Manager, Resource Management Jonathan Gillingham.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this Report. Your attention to this matter is appreciated.

If you have any questions, please contact me by phone at 1-867-587-7205 or by email at Jonathan_Gillingham@gov.nt.ca.

Sincerely,

A handwritten signature in black ink that reads "Jonathan Gillingham".

Jonathan Gillingham
Manager of Resource Management
Department of Lands
Sahtu Region

CC: Sathu Land and Water Board
Trevor Bremner – Regional Superintendent, Sahtu Region



ENVIRONMENTAL INSPECTION REPORT

Permittee:	HRN Contracting Limited	Permit Expiry Date:	December 02, 2018
Land Use Permit No.	S13Q-004	Previous Inspection:	June 07, 2017
Quarrying Permit No.	2013QP0099	Inspection Date:	September 01, 2020
Contractor:	N/A	Subcontractor:	N/A
Location(s) Inspected:	Quarry		
Current Stage of Operation:	Currently not in use		
Program Modifications Approved:	None		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Quarry				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	N/A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	N/A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	N/A				
Historical / Archaeological Sites	A				
Ecological Resources	N/A				
Fuel Storage	N/A				
Brush Disposal	A				
Restoration of Lands	U				
Permits	N/A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

Quarry:

During the inspection, Inspector has found no change to the site regarding the remediation requested at the quarry entrance. The erosion issues mentioned in the last Inspection Report (June 19, 2017) still exist. The Permittee has received an unacceptable condition regarding permitted condition **26 (1)(O) 2**, "Prior to the expiry date of this Permit, the Permittee shall complete all cleanup and restoration of the land used." This Permit expired on December 2, 2018; the highlighted erosion issues have not been addressed. Until the Permittee finishes the required remediation of the erosion issues and the entire quarry, this condition will remain unacceptable.

The last Inspection Report (June 19, 2017) had requested the Permittee send a Remediation Plan with a list of actions and a timeline. If the Permittee intends to apply for a new Permit,

Date:	September 01, 2020	Permit #:	S13Q-004	Page No:	1
-------	--------------------	-----------	----------	----------	---



ENVIRONMENTAL INSPECTION REPORT

the Inspector expects this to be included in the Project Description Report. Clarify the methodology of how the Permittee will address the erosion issues and supply a timeline.

General Comments:

In discussion with the Permittee, the Permittee intended to fix these issues over the winter season of 2019. Unfortunately, due to unforeseen circumstances, this did not occur. Inspector encourages the Permittee to discuss reapplying for a new Land Use Permit and Quarry Permit because both Permits have expired.

Please contact our office to discuss the next steps; my contact information can be found in the cover letter of this Report.

N/A

Representative Signature

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Aerial view of quarry



Figure 2

Aerial view of quarry





ENVIRONMENTAL INSPECTION REPORT

Figure 3

Aerial view of quarry



Figure 4

Aerial view of quarry

